

1. APPLICABILITY

Bugatti Chiron Super Sport

2. VIN RANGE

- List at the end of the document.
- Contact your BUGATTI Regional service manager.

3. MARKET REGION

All <input type="checkbox"/>			
North America <input checked="" type="checkbox"/>	Middle East <input type="checkbox"/>	Europe <input checked="" type="checkbox"/>	Japan <input type="checkbox"/>

4. BULLETIN OBJECT

The wheels must be replaced on the concerned vehicle.

5. DESCRIPTION

During the final production validation, it was observed a set of non-homologated rims 5B4 601 025 (Front Sport rims) and 5B4 601 026 (Rear Sport rims) had been configured and assembled to a Chiron Super Sport. These Chiron Sport rim types are not validated on Chiron Super Sport.

!!! Each concerned vehicle must have a new set of wheels !!!



Chiron Sport Wheel design overview

Warning:



Comply with the vehicle preparation measures for maintenance and repair procedures. Refer to the official Workshop Manual, "General instructions about the vehicle".


If in any doubt regarding this procedure, please contact your Bugatti regional after sales manager with questions regarding the procedure.

6. REQUIRED SPECIAL TOOLS/PARTS

See list of necessary parts:

Designation	Quantity	Reference
Front wheel	2	-
Rear wheel	2	-
Valve	4	5B4601361
Sensor	4	5B4907275
Front tire	2	5B4601327C
Rear tire	2	5B4601329D

7. OPERATION

-  - Comply with the instructions in the chapter "General instructions" → **page 27.**
- Following the workshop manual instruction for every operation
- Cleanliness must be ensured all along the procedure.



Please follow the concerned vehicle list to perform the operation.



- 7.1 Replace the front and rear wheels and tighten them to the appropriate torque (Workshop manual > Chassis).
- 7.2 Check the tire pressures and adjust it if necessary.
- 7.3 Open a technical ticket to provide the serial number of the old and new wheels.
- 7.4 Old wheels sets **must be sent back to the factory.**

WARRANTY INFORMATION

Operation	Repair code	Time
Rims replacement	BUGCR034	1,5 Hrs

Bugatti Bulletins are intended for use by experienced and trained technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to an Authorized Bugatti Partner. See your Bugatti Partner for advice on whether your vehicle may benefit from the information contained within this document.

The information contained in this Bulletin is accurate at the date of publication. However, Bugatti Automobiles S.A.S. regularly updates technical information. Please check with your Bugatti Partner that the Bulletin you intend to use contains the latest available information.

© Bugatti Automobiles S.A.S. All Rights Reserved

Field Technical Information versions history		
Version	Modification	Author
V1.0	Creation of the file	L.SANDT
V1.1	Amendment based on BEW feedback	T.HODGSON-PHILLIPS

VIN RANGE

This table represents the VIN numbers concerned by this Recall campaign:

Short VIN
S7.043
S7.054
S7.061
S7.064