

SAFETY RECALL

NORTH AMERICA

Rear Coil Spring

Reference: 64A



FCA US LLC

Template Version 1.0

Revision	Edition	Detail
5	January 2026	64A Superseded.

Effective immediately the Open VINs in Safety Recall 64A have been superseded to Safety Recall 20D. Please see Safety Recall 20D for campaign information and service repair instructions, once available. Repaired VINs will retain record of 64A, but no additional repairs should be done using 64A procedure/parts.

NOTE: No repairs should be made using lower spring isolator 68375896AC or 68375896AD.