Technical Instructions

Safety Recall SR-23-02-0

Rear-View Image

Model: Air

Year: 2022 / 2023


Market: USA

Rev 1

Release Date: 09/15/2023

Entire Page Confidential Business Information - 49 CFR part 512

I. PROCESS OVERVIEW



II. VIN ELIGIBILITY

Model	Year	Market	
Air	2022 /2023	USA	



Entire Page Confidential Business Information - 49 CFR part 512

III. WORK ORDER DOCUMENTATION

Include the following information in the work order:

Concern	The rear-view camera image may intermittently not display after shifting vehicle into reverse	
Cause	Vehicle operating on software version between v2.0.15 – v2.0.50	
Correction Update to the most current software version		

IV. DOCUMENTATION DETAILS

To ensure that vehicle campaign repairs are documented correctly, please reference the following when creating work orders for SR-23-02-0:

Job Code	SR-23-02-0 Rear-View Image	
Day Tyma	Campaign [Customer Cars]	
Pay Type	Rectify [Lucid Internal Vehicles]	
Defect Code	Campaign	
Causal PN	P11-K2B000	

Use the following Labor Op Code:

Labor Op Code	Description	FRT*
96.230201	SR-23-02-0 Rear-View Image – Software Update	0.8

^{*}Flat Rate Time (FRT) is subject to change

NOTE: Safety Recall Campaign claim should be submitted as "CAMPAIGN" Pay Type

V. IMPORTANT INFORMATION

ACAUTION: Ensure the use of all appropriate PPE when performing this repair.

VI. REPAIR INSTRUCTIONS

1. Use latest Technical Instructions (TI)

Use the latest revision Technical Instructions (TI) by checking the revision (REV) number displayed on the title page and in the document footer.

2. Confirm VIN Eligibility

Eligible VIN will have an open Service Campaign Asset in Salesforce.

Title: SR-23-02-0 Rear-View Image

Document: 19467



Entire Page Confidential Business Information - 49 CFR part 512

VII. SOFTWARE UPDATE

1. Update Vehicle Software

Follow the instructions in the Service Manual to update the vehicle's software to the most current version available.

Service Manual / Inspection / Over the Air (OTA) Flashing

- 2. Check and clear DTCs. Refer to DTCs Check and Clear
- 3. Perform a minimum of five (5) shifts into "Reverse" to confirm the rear-view image displays within 2 seconds after shifting into "Reverse". If the reverse image does not appear, open an FTS Escalation Case.
- 4. No further action required. The campaign is complete. Release vehicle.

Document: 19467