

# Recall Campaign Bulletin



Mercedes-Benz

Campaign No. 2023100011, October 2023

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model EQB (243 platform)**  
**Model Year 2022**

## **Replace Child Seat Anchor Covers on the Second-Row Seats**

Mercedes-Benz AG (“MBAG”), the manufacturer of Mercedes-Benz vehicles, has determined that on one Model Year (“MY”) 2022 EQB (243 platform) vehicle, the symbol on the child seat anchor covers on the second-row seats might not meet current specifications. The functionality of the child seat anchor covers to attach to the rear seat cushion is ensured. However, certain requirements of FMVSS 225 might not be fulfilled. In the event the symbol on the child seat anchor covers is not according to FMVSS 225 specifications, a customer may incorrectly install the child seat in the vehicle. Incorrect installation of a child seat might increase the risk of injuries to occupants. An authorized Mercedes-Benz dealer will replace the child seat anchor covers on the rear seats of the affected vehicle.

Prior to performing this Campaign:

- VMI must be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for other open campaign(s) and perform accordingly.
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.

Approximately 1 vehicle is affected.

Order No. P-RC-2023100011

# Recall Campaign Bulletin

Recall Campaign Bulletin

Recall Campaign Bulletin

Recall Campaign Bulletin

Recall Campaign Bulletin

## Replace Child Seat Anchor Covers on the Second-Row Seats

---

### Check Procedure

1. Check which version of the child seat anchor covers *has been* installed in the vehicle. (i-Size or ISOFIX).



**Picture 1**  
Code 8U8: **Not OK** (i-Size version)

**Picture 2**  
WITHOUT code 8U8: **OK** (Isofix version)

2. Check child seat anchor covers type (**4 pieces**) on the rear seats of the vehicle.

**i** The child seat anchor covers installed in the vehicle **must** be the ISOFIX version.

- a. Installed child seat anchor covers type: Isize (**Picture 1**): Carry out **work procedure**.
- b. Installed child seat anchor covers type: ISOFIX (**Picture 2**): **End measure**.

### Work Procedure

1. Replace child seat anchor covers.

**i** Use a suitable tool to release and remove the child seat anchor covers in the area of the arrow (**Figure 3**).



**Figure 3**

**Primary Parts Information**

Qty.	Part Name	Part Number
As required	Child seat anchor cover	A 247 860 83 02 8T92

*The replacement parts must be determined according to the equipment variant for the vehicle identification number via the parts process in the Xentry Portal.*

**i** **Note:** *The following allowable labor operation should be used when submitting a warranty claim for this repair:*

**Warranty Information**

Damage Code	Operation Number	Description	Labor Time (hrs.)
91 950 03	12-1893	Check child seat anchor covers on second-row seats	0.1
	12-1894	Replace (up to 4) child seat anchor covers on second-row seats (after check)	0.1

**i** **Note:** *Always check Xentry Operation Time (XOT) for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.*