 Tesla, Inc. Service Bulletin		<h2>Update Vehicle Software to Incorporate Additional Autosteer Controls</h2>	
SB-23-00-008 December 20, 2023			
Classification		Section/Group	Mobile Service
Recall Bulletin		00 - Inspection & Service	Can Perform (where permitted)
Model Year	Model	Country/Region	Build Location
2012 - 2023	Model S, Model X, Model 3, Model Y	United States, Canada	Fremont, Giga Austin, Giga Shanghai
<small>The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.</small>			

Recall Bulletin: Recall Bulletins are mandatory service procedures that, unless they can be completed via a software update that a customer installs through the normal course of ownership, must be carried out by Tesla-certified Service Centers. Recall work performed by uncertified technicians could lead to unsafe conditions or voided warranty provisions.

Condition

On some vehicles, in certain circumstances when Autosteer is engaged, the prominence and scope of the feature's controls may not be sufficient to prevent driver misuse of this feature.

Correction


Inspect the vehicle software version, and if necessary, update the vehicle software to version 2023.44.30 or later.

Correction Description	Correction	Time
Inspect Vehicle Software Version; No Update Necessary	S012300008	0.06
Inspect And Update Vehicle Software To Mitigate Autosteer Misuse	S022300008	0.06

Procedure

On the vehicle touchscreen, touch **Controls** (vehicle icon) > **Software**, and then scroll down to display the vehicle software version.

- If the vehicle is operating with software version 2023.44.30 or later, no further action is necessary. Use correction code S012300008.
- If the vehicle is operating with a software version earlier than 2023.44.30, update the software to version 2023.44.30 or later (refer to Service Manual procedure 00020003; [Legacy Model S](#), [Legacy Model X](#), [Model 3](#), [Model Y](#), [Palladium Model S](#), [Palladium Model X](#)). Use correction code S022300008.

 **NOTE:** Legacy Model S and Model X vehicles equipped with DAS 1.0 or 2.0 do not have a vehicle software version yet available. A future revision of this document will cover these vehicles. Leave this bulletin open for such vehicles in SCA at this time.