
October 23, 2024Version 8

Safety Recall: Multi-Model Acura Fuel Pump Motor Stop Sale

This service bulletin has been replaced by the service bulletins identified below.

APPLIES TO

All affected vehicles have moved from this bulletin to the following service bulletins identified below. Vehicles are still considered **Stop Sale** until they are repaired under the new remedy service bulletin:

- 24-043 Safety Recall: 2013 MDX Fuel Pump Module Set/Assembly
- 24-029 Safety Recall: 2014-15 RLX Fuel Pump Module Set/Assembly
- 24-019 Safety Recall: 2018-19 RLX Fuel Pump Motor
- 24-011 Safety Recall: 2015-20 TLX SH-AWD Fuel Pump Motor
- 24-010 Safety Recall: 2017-20 NSX Fuel Pump Motor
- 24-008 Safety Recall: 2016-20 ILX Fuel Pump Motor
- 24-007 Safety Recall: 2015-20 TLX (Without SH-AWD) Fuel Pump Motor
- 24-006 Safety Recall: 2014-20 MDX and 2018-20 MDX Sport Hybrid Fuel Pump Motor
- 24-005 Safety Recall: 2019-20 RDX Fuel Pump Motor
- 24-034 Safety Recall: 2018-20 RLX Sport Hybrid Fuel Pump Motor

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by “do-it-yourselfers,” and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.