



February, 2025

*** * * IMPORTANT SAFETY RECALL REMINDER * * ***

According to our records, your 2022 Bronco has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number **23S06 - Potential Roll In Park**
and Description:

What is the issue? On your vehicle, there may be a loose (extra) bolt inside the transmission assembly.
A loose bolt inside the transmission could prevent the transmission from achieving park by blocking the park pawl from engaging the park gear, although the gear shifter position may indicate that the vehicle has been shifted to "PARK." Loss of the ability to secure the park pawl could result in unintended vehicle movement, increasing the risk of a crash or injury.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**.

If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Febrero de, 2025

*** * * RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD * * ***

SegUR nuestros registros, no se realizaron en sur 2022 Bronco las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **23S06 - Posible desplazamiento en Estacionamiento**

¿Cuál es el problema? Es posible que haya un tornillo flojo (adicional) en el interior del ensamble de la transmisión de su vehículo.

Un tornillo flojo en el interior de la transmisión podría impedir que la transmisión logre el estacionamiento al bloquear el trinquete de estacionamiento y no dejar que el engrane se acople en estacionamiento, a pesar de que la posición del cambiador de velocidades podría indicar que el vehículo ha sido cambiado a "ESTACIONAMIENTO". La pérdida de la capacidad de asegurar el trinquete de estacionamiento podría generar un movimiento no intencionado del vehículo, lo cual aumenta el riesgo de choque o de sufrir lesiones.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**.

Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.


Gracias por su atención en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C


0105549 A / 000000000000659 / 659



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▼ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▼



▼ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▼