



July, 2024

**\* \* \* IMPORTANT SAFETY RECALL REMINDER \* \* \***

According to our records, your 2023 Transit has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number**    **23S04 - 2023 Transit Fuel Tank Thermocouple Dislodged**  
**and Description:**

**What is the issue?**            On your vehicle, it may be possible a Grade Vent Valve (GVV) was not properly welded to the fuel tank shell. Over time, the weld between the fuel tank shell and the GVV may separate.

An inadequate weld between the grade vent valve and the fuel tank shell may be insufficient to prevent a fuel leak during a crash. A fuel leak in the presence of an ignition source increases the risk of a fire.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [ford.com/support](http://ford.com/support).

Thank you for your attention to this very important matter.

Julio de, 2024

**\* \* \* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \* \* \***

SegUR nuestros registros, no se realizaron en sur 2023 Transit las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:**            **23S04 - Transit 2023 termopar del tanque de combustible desprendido**

**¿Cuál es el problema?**            En su vehículo, es posible que una válvula de ventilación secundaria (GVV) no se haya soldado correctamente en la carcasa del tanque de combustible. Con el tiempo, la soldadura entre la carcasa del tanque de combustible y la GVV se podría separar.

Una soldadura inadecuada entre la válvula de ventilación secundaria y la carcasa del tanque de combustible podría ser insuficiente para evitar una fuga de combustible durante un choque. Una fuga de combustible en presencia de una fuente de encendido aumenta el riesgo de incendio.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [ford.com/support](http://ford.com/support).

Gracias por su atenciic en este asunto sumamente importante.



P. O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

0456496 A / 000000000000432 / 432



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶  
REMOVE THESE SIDE EDGES FIRST

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶  
REMOVE THESE SIDE EDGES FIRST

