



IMPORTANT SAFETY RECALL NOTICE SECOND NOTICE - ACTION REQUIRED

October 10, 2024

(First Name),

Our records currently indicate you have not had this recall completed on your affected vehicle:

T-23-01

Polaris has determined that on some Model Year 2022 and 2023 Slingshot S, SL, SLR, and R vehicles, the alternator may have been improperly manufactured by the supplier and may crack and separate during operation, posing a fire hazard and risk of serious injury.

Contact your authorized Polaris dealer to schedule an appointment to have the repairs performed. If you need assistance contacting or locating a Polaris dealer, visit our [Dealer Locator](#) web page.

This work will be performed by your dealer at no cost to you.

For the latest update on this safety recall, visit our [Product Safety Recall](#) web page.

We apologize for this inconvenience and assure you that we are committed to customer satisfaction for riders to enjoy.

-Polaris Slingshot

Received This Notice In Error?

This notice was sent according to our most current registration information. If you no longer own this vehicle, contact your dealer to complete a transfer of ownership. Federal law requires that any vehicle lessor receiving this notice must forward a copy of this notice to the lessee within 10 working days after the day on which the notice is received.

You've received this email from Polaris because you are a registered owner of a vehicle affected by a recent safety recall notice.

Please do not reply to this email. To contact us, please call us at **1-800-POLARIS** or visit our [help page](#).