



August, 2025

**\* \* \* IMPORTANT SAFETY RECALL REMINDER \* \* \***

According to our records, your 2006 Ranger has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number and Description:** **23S08 - Passenger Frontal Airbag Inflator Repairs (Post FSA 17S42, 18S02)**

**What is the issue?** On your vehicle, the replacement frontal passenger airbag inflator may have been installed in the incorrect orientation during a previously executed repair for Field Service Action (FSA) 17S42 or 18S02.

If a previously remedied vehicle has a mis-installed passenger airbag inflator and is in a crash event necessitating deployment of the passenger airbag, the airbag may not deploy as intended, increasing the risk of injury.

If you have questions or concerns, please contact our **Ford Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [ford.com/support](http://ford.com/support).

Thank you for your attention to this very important matter.

Augusto de, 2025

**\* \* \* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \* \* \***

SegUR nuestros registros, no se realizaron en sur 2006 Ranger las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:** **23S08 - Reparaciones del inflador de la bolsa de aire delantera del pasajero (publicación FSA 17S42,18S02)**

**¿Cuál es el problema?** En su vehículo, el inflador de la bolsa de aire del pasajero delantero de reemplazo pudo haber sido instalado en la orientación incorrecta durante una reparación ejecutada anteriormente en la Acción de servicio en campo (FSA) 17S42 o 18S02.

Si un vehículo reparado anteriormente con un inflador de la bolsa de aire del pasajero instalado incorrectamente se ve involucrado en un choque que requiera el despliegue de la bolsa de aire del pasajero, esta podría no desplegarse según lo previsto, lo cual aumenta el riesgo de sufrir lesiones.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [ford.com/support](http://ford.com/support).


Gracias por su atención en este asunto sumamente importante.



P. O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

0000316 A / 000000000000343 / 343



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶  
REMOVE THESE SIDE EDGES FIRST

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶  
REMOVE THESE SIDE EDGES FIRST

