



February, 2025

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2020 Corsair has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: **23S23 - Back-Up Screen Failures**

What is the issue? You may intermittently experience a rear camera blue or black image on the SYNC screen when the vehicle is placed in reverse or when the 360 degree view is selected and available (during low-speed operation). Once displayed, the rear camera blue or black image may persist for the remainder of the ignition ON cycle. Once present, the issue is likely to reoccur on subsequent key cycles.

The loss of the rear camera image while in reverse increases the risk of a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**.

If you wish to contact us through the Internet, our address is: lincoln.com/support.

Thank you for your attention to this very important matter.

Febrero de, 2025

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2020 Corsair las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **23S23 - Desperfectos en la pantalla de retroceso**

¿Cuál es el problema? Es posible que experimente, de forma intermitente, una imagen azul o negra de la cámara trasera en la pantalla de SYNC cuando el vehículo se coloca en reversa o cuando se selecciona y está disponible la vista de 360 grados (durante funcionamiento a baja velocidad). Una vez visualizada, la imagen azul o negra de la cámara trasera podría permanecer durante el recordatorio del ciclo de encendido. Una vez presente, es posible que el problema vuelva a ocurrir en los siguientes ciclos de la llave.

La pérdida de la imagen de la cámara trasera mientras está en reversa aumenta el riesgo de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**.

Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: lincoln.com/support.

Gracias por su atención en este asunto sumamente importante.




THE LINCOLN MOTOR COMPANY

P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0028190 A / 000000000000691 / 691



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

