



December, 2024

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2023 F-350 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number 23S22 - 2023 F250-600 Steering I-Shaft OSM Concern
and Description:

What is the issue? The steering column upper shaft coupler bolts may not have been re-installed or torqued to specification at the plant.

A missing or improperly torqued bolt that secures the steering column upper shaft coupler can result in separation of steering system adjoining components, resulting in loss of steering control, which can increase the risk of a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

December de, 2024

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2023 F-350 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: 23S22 - F250-600 2023 - Preocupación por OSM del eje I de dirección

¿Cuál es el problema? Los tornillos del acoplador de la flecha superior de la columna de la dirección no se reinstalaron o apretaron según la especificación en la planta.

Si un tornillo que fija el acoplador de la flecha superior de la columna de la dirección no está presente o se ha apretado incorrectamente, se podría ocasionar la separación de los componentes adyacentes del sistema de dirección, lo cual genera una pérdida de control de la dirección y puede aumentar el riesgo de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.

Gracias por su atención en este asunto sumamente importante.



P. O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0581627 A / 000000000000976 / 976



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶
REMOVE THESE SIDE EDGES FIRST

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶
REMOVE THESE SIDE EDGES FIRST

