



February, 2026

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2022 F-150 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: **23S30 - Rear Light Bar Cracks and Water Intrusion**

What is the issue? On your vehicle, it may be possible that your reversing lamps may not function due to microscopic cracks that can develop in the vehicle's rear lightbar. If a microscopic crack is present, condensation can potentially enter the reversing lamp lens through these cracks and cause electrical failure to the reverse lamps.

This may result in inoperative reverse lamps which can reduce the awareness of other motorists or road users of the driver's intention to operate the vehicle in reverse gear, increasing the risk of injury or crash.

If you have questions or concerns, please contact our **Ford Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Febrero de, 2026

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2022 F-150 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **23S30 - Grietas en la barra de luz trasera e intrusión de agua**

¿Cuál es el problema? Es posible que las luces de reversa de su vehículo no funcionen debido a fisuras microscópicas que se desarrollan en la barra de luz trasera. Si hay una fisura microscópica presente, a través de esta podría entrar condensación en la mica de las luces de reversa y provocar una falla eléctrica en las luces de reversa.

Esto podría traducirse en luces de reversa que no funcionan, con cual otros motoristas o usuarios de la vía podrían no percatarse de la intención del conductor de usar el engrane de reversa del vehículo, lo cual aumenta el riesgo de sufrir lesiones o choques.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.

Gracias por su atenciic en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0001403 A / 000000000000572 / 34



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

