



February, 2025

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2023 Nautilus has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: **23S32 - Rear Shock Improper Crimp**

What is the issue? On your vehicle, it may be possible that a rear shock with a defective rod stopper crimp was installed. The shock may be over-extended in certain driving conditions which may result in damage to the brake hose, rear axle half shaft, wheel speed sensor and stabilizer bar link.

A damaged brake hose can extend vehicle stopping distance, increasing the risk of a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: lincoln.com/support.

Thank you for your attention to this very important matter.

Febrero de, 2025

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2023 Nautilus las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **23S32 - Engarce incorrecto del amortiguador trasero**

¿Cuál es el problema? Es posible que en su vehículo se haya instalado un amortiguador trasero con un engarzador del tope de la varilla defectuoso. El amortiguador podría extenderse en exceso en determinadas condiciones de manejo, lo cual podría generar daños en la manguera del freno, la semiflecha del eje trasero, el sensor de velocidad de la rueda y el eslabón de la barra estabilizadora.

Una manguera de freno dañada puede ampliar la distancia de detención del vehículo, lo cual aumenta el riesgo de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: lincoln.com/support.

Gracias por su atenciic en este asunto sumamente importante.




THE LINCOLN MOTOR COMPANY

P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0523518 A / 000000000000803 / 803



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

