



March, 2025

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2023 F-150 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number **23C32 - Electronic Cabin Coolant Heater Module Missing Solder Issue**
and Description:

What is the issue? On your vehicle, the electronic cabin coolant heater module may have a missing solder joint, which can result in intermittent, or no windshield defrost and defog functionality. You may also notice a lack of heat in the vehicle cabin when the heater is on.

The lack of a functioning windshield defrosting and defogging system may decrease the driver's visibility under certain driving conditions, increasing the risk of a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Marzo de, 2025

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2023 F-150 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **23C32 - Problema de soldadura faltante en el módulo del calentador electrónico del refrigerante de la cabina**

¿Cuál es el problema? Es posible que el módulo electrónico del calentador del refrigerante de la cabina le falte una junta de soldadura, lo que puede provocar que la función de descongelación y desempañamiento del parabrisa sea intermitente o nula. También puede observar una falta de calor en la cabina del vehículo cuando la calefacción está activada.

Si el sistema de desempañador y descarchador del parabrisa no funciona, la visibilidad del conductor en determinadas condiciones de conducción podría verse reducida, lo cual aumenta el riesgo de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.


Gracias por su atenciic en este asunto sumamente importante.



P. O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0670417 A / 000000000000511 / 511



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▼
REMOVE THESE SIDE EDGES FIRST

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▼
REMOVE THESE SIDE EDGES FIRST

