



September, 2026

**\*\*\* IMPORTANT SAFETY RECALL REMINDER \*\*\***

According to our records, your 2023 F-350 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number**    **23S63 - Manufacturing Clockspring Contamination**  
**and Description:**

**What is the issue?**



Airbag Warning Indicator

On your vehicle, an insufficient weld in your steering wheel clock spring may lead to a loss of electrical circuit connection with your steering wheel and the driver's front airbag. If this occurs, the airbag warning light in the vehicle's instrument cluster (shown on the left) will illuminate.

You may also notice the loss of illumination and function of switches on the steering wheel (e.g. radio controls) or an inoperative horn.

If the airbag circuit disconnects, and a crash event of sufficient severity warrants a driver front airbag deployment, that airbag will not deploy. A driver airbag that does not deploy when intended increases the risk of injury in a crash.

If you have questions or concerns, please contact our **Ford Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [ford.com/support](https://ford.com/support).

Thank you for your attention to this very important matter.

Septiembre de, 2026

**\*\*\* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \*\*\***

Según nuestros registros, no se realizaron en su 2023 F-350 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:**    **23S63 - Contaminación del resorte de reloj de fábrica en vehículos**

**¿Cuál es el problema?**



Indicador de alerta de bolsa de aire

Una soldadura insuficiente en el resorte de reloj del volante de dirección de su vehículo podría provocar una pérdida de conexión del circuito eléctrico con el volante de dirección y la bolsa de aire delantera del conductor. Si esto ocurre, se encenderá la luz de alerta de bolsa de aire en el tablero de instrumentos del vehículo (que se muestra a la izquierda).

También podría observar la pérdida de iluminación y de función de los interruptores en el volante de dirección (por ejemplo, los controles de la radio) o el claxon que no funciona.

Si se desconecta el circuito de la bolsa de aire, en caso de ocurrir un choque de suficiente intensidad donde el despliegue de la bolsa de aire delantera del conductor debiese producirse, esa bolsa de aire no se desplegará. Cuando una bolsa de aire del conductor que no se despliega según lo previsto, el riesgo de sufrir lesiones en un choque aumenta.

Si tiene preguntas o inquietudes, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [es.ford.com/support](https://es.ford.com/support).

Gracias por su atención en este asunto sumamente importante.



P. O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

0005951 A / 000000000000026 / 26



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▼ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▼

▼ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▼

