

May 30, 2025

Version 6

Safety Recall: 2018–20 Odyssey Front Seat Belt Buckle Repair

This Service Bulletin was replaced by Service Bulletins 25-035, Safety Recall: 2018-20 Odyssey Driver's Seat Belt Buckle Replacement and 25-034, Safety Recall: 2018-20 Odyssey Passenger's Seat Belt Buckle Replacement dated May 30, 2025

AFFECTED VEHICLES

Year	Model	Trim Level	VIN Range
2018–20	Odyssey	ALL	Check the iN VIN status for eligibility.


BACKGROUND

Due to improper manufacturing of the seat belt buckle channel, the front seat belt buckles may not latch properly. An improperly latched seat belt buckle may not securely restrain occupant(s) in position during a collision.

WARRANTY CLAIM INFORMATION

For repairs **before or on May 29, 2025**, you must use the warranty claim information within this bulletin. For repairs **on or after May 30, 2025**, go to the respective Service Bulletins mentioned above, depending on the required repair.

TEST CODE FIELD



The screenshot shows a software interface for repair information. A dashed box highlights the 'Test Code' field, which is currently empty. An arrow points from the 'TEST CODE FIELD' label above to this field. Below the 'Test Code' field is a table with columns for 'Item', 'Labor Operation No.', 'Labor Description', and 'Time'. The first row shows item 1 with labor operation 8555A6 and a time of 0.4. The second and third rows are empty. At the bottom, there are fields for 'On' (set to NO) and 'Diagnostic Trouble Codes'.

Seat Belt Button Repair

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
8555A6	Driver Seat belt Button Replace (Includes: Function, DTC Indicator, and Residue check).	0.4hr	6XL00	MDD00	A23001A	04816-TVA-A20ZA
8655A2	Passenger Seat belt Button Replace (Includes: Function, DTC Indicator and Residue check).	0.4hr	6XR00	YDI00	A23001B	04813-TVA-A10ZA

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by “do-it-yourselfers,” and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

Seat Belt Buckle Replacement + Inspection

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
8551F6	Driver Seat belt Buckle Replace (Includes: Inspection).	0.5hr			A23001C	
A	For Buckle causing DTC check and troubleshooting only (any other DTC normal troubleshooting applies).	0.3hr	6XL00	MDD00	A23001D	04816-TVA-A20ZA
8651A5	Passenger Seat belt Buckle Replace (includes Inspection, Seat Weight Calibration and steering angle learn).	0.6hr			A23001E	
A	For Buckle causing DTC check and troubleshooting only (any other DTC normal troubleshooting applies).	0.3hr	6XR00	YDI00	A23001F	04813-TVA-A10ZA

NOTE:

- Due to seat belt part number variation for each model trim, you may add the seat belt part number to the template.