

May 30, 2025

Version 6

## Safety Recall: 2019 Insight Front Seat Belt Buckle Repair

This Service Bulletin was replaced by Service Bulletins 25-037, Safety Recall: 2019 Insight Driver's Seat Belt Buckle Replacement and 25-036, Safety Recall: 2019 Insight Passenger's Seat Belt Buckle Replacement dated May 30, 2025.

### AFFECTED VEHICLES

Year	Model	Trim Level	VIN Range
2019	Insight	ALL	Check the iN VIN status for eligibility.


### BACKGROUND

Due to improper manufacturing of the seat belt buckle channel, the front seat belt buckles may not latch properly. An improperly latched seat belt buckle may not securely restrain occupant(s) during a collision, increasing the risk of injury.

### WARRANTY CLAIM INFORMATION

For repairs **before or on May 29, 2025**, you must use the warranty claim information within this bulletin. For repairs on or **after May 30, 2025**, go to the respective Service Bulletins mentioned above, depending on the required repair.

TEST CODE FIELD



### Seat Belt Button Repair

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
8555A6	Driver Seat Belt Button Replace (Includes: Function, DTC Indicator, and Residue check).	0.4hr	6XL00	BDC00	A23003A	04816-TVA-A20ZA
8655A2	Passenger Seat Belt Button Replace (Includes: Function, DTC Indicator, and Residue check).	0.4hr	6XR00	ODH00	A23003B	04813-TVA-A10ZA

**CUSTOMER INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by “do-it-yourselfers,” and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

### Seat Belt Buckle Replacement + Inspection

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
8551F6	Driver Seat Belt Buckle Replace (Includes: Inspection).	0.6 hr	6XL00	BDC00	A23003C	04816-TVA-A20ZA
A	For Buckle causing DTC check and troubleshooting only (any other DTC normal troubleshooting applies).	0.3 hr			A23003D	
8651A5	Passenger Seat Belt Buckle Replace (Includes: Inspection, seat weight calibration, and steering angle learn).	0.7 hr	6XR00	ODH00	A23003E	04813-TVA-A10ZA
A	For Buckle causing DTC check and troubleshooting only (any other DTC normal troubleshooting applies).	0.3 hr			A23003F	

**NOTE:**

- Due to seat belt part number variation for each model trim, you may add the seat belt part number to the template.