

May 30, 2025

Version 6

Safety Recall: 2019–20 RDX Front Seat Belt Buckle Repair

This Service Bulletin was replaced by Service Bulletins 25-020, Safety Recall: 2019-20 RDX Driver's Seat Belt Buckle Replacement and 25-019, Safety Recall: 2019-20 RDX Passenger's Seat Belt Buckle Replacement dated May 30, 2025.

AFFECTED VEHICLES

Year	Model	Trim Level	VIN Range
2019–20	RDX	ALL	Check the iN VIN status for eligibility.

BACKGROUND

Due to improper manufacturing of the seat belt buckle channel, the front seat belt buckles may not latch properly. An improperly latched seat belt buckle may not securely restrain occupant(s) during a collision, increasing the risk of injury.

WARRANTY CLAIM INFORMATION

For repairs before or on May 29, 2025, you must use the warranty claim information within this bulletin. For repairs on or after May 30, 2025, go to the respective Service Bulletins mentioned above, depending on the required repair.

TEST CODE FIELD

The screenshot shows a software interface for repair information. At the top, there is a 'Repair Information' header with a 'View Flat Rate Labor Time' checkbox. Below this, a 'Test Code' field is highlighted with a red dashed border and a red circle, with an arrow pointing to it from the label 'TEST CODE FIELD' above. The main table has columns for 'Item', 'Labor Operation No.', 'Labor Description', and 'Time'. The first row shows item 1 with labor operation 8555A6 and a time of 0.4. Below the table, there are fields for 'On' (set to NO) and 'Diagnostic Trouble Codes'.

Seat Belt Button Repair

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
8555A6	Driver Seat Belt Button Replace (Includes: Function, DTC Indicator, and Residue check).	0.4 hr	6XL00	LD900	B23005A	04816-TJB-A00ZB
8655A2	Passenger Seat Belt Button Replace (Includes: Function, DTC Indicator, and Residue check).	0.4 hr	6XR00	ZDE00	B23005B	04813-TJB-A00ZB

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by “do-it-yourselfers,” and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.

Seat Belt Buckle Replacement + Inspection

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
8551F6	Driver Seat Belt Buckle Replace (Includes: Inspection).	0.5 hr	6XL00	LD900	B23005C	04816-TJB-A00ZB
A	For Buckle causing DTC check and troubleshooting only (any other DTC normal troubleshooting applies).	0.3 hr			B23005D	
8651A5	Passenger Seat Belt Buckle Replace (Includes: Inspection, seat weight calibration, and steering angle learn).	0.6 hr	6XR00	ZDE00	B23005E	04813-TJB-A00ZB
A	For Buckle causing DTC check and troubleshooting only (any other DTC normal troubleshooting applies).	0.3 hr			B23005F	

NOTE:

- Due to seat belt part number variation for each model trim, you may add the seat belt part number to the template.