

# 23PBG: Interim Safety Bulletin - Dana Driveline Weld

---

## Number

[Edit](#) [Clone](#)

23PBG / 23V616 / 2023-496

---

## Supplier

Dana

---

## Description

Dana Driveline Weld

---

## Date

9/22/2023

---

## What's New

### Interim Safety Recall

On certain Peterbilt model 220 chassis equipped with Dana SPL100 drivelines, the driveline tube seam weld may separate or tear under certain stress loads, resulting in driveline separation and sudden loss of drive power. A sudden loss of drive power may increase the risk of a crash.

**At this time, parts are not yet available to complete the necessary repairs. Once parts become available, this bulletin will be updated.**

## Introduction

---

On certain Peterbilt model 220 chassis the driveline tube seam weld may separate or tear under certain stress loads, resulting in driveline separation and sudden loss of drive power. A sudden loss of drive power may increase the risk of a crash.

There will be no noticeable signs/indications preceding the described failure.

Reference Dana recall **23E052** for more information.

**At this time, parts are not yet available to complete the necessary repairs. Once parts become available, this bulletin will be updated.**

## Situation

---

**22** (18 U.S., 4 Canada) Model year 2023, Peterbilt model 220 chassis built from 08/29/22 through 10/07/22 equipped with Dana SPL100 drivelines with suspect driveline serial numbers

## Resolution

---

### Interim Safety Recall

**At this time, parts are not yet available to complete the necessary repairs. Once parts become available, this bulletin will be updated.**

## Federal Law

---

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

## Links

---

[23PBG Chassis List](#)

[23PBG INTERIM US Customer Letter](#)

[23PBG INTERIM Canada Customer Letter](#)

[23PBG INTERIM Canada French Customer Letter](#)

