



Navistar, Inc.  
2701 Navistar Drive  
Lisle, IL 60532 USA

navistar.com



A NAVISTAR COMPANY

**IMPORTANT SAFETY RECALL 23514  
UPDATED INTERIM NOTICE  
NHTSA RECALL NO. 23V-353**

**SEPTEMBER 2023**

**This notice applies to your vehicle identified on the enclosed card.**

Dear INTERNATIONAL® Customer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Navistar has decided certain 2001 thru 2003 9100i model trucks built 06/09/2000 thru 11/01/2002, 2001 thru 2010 9200i model trucks built 05/16/2000 thru 02/24/2009, 2008 thru 2018 ProStar® model trucks built 09/28/2006 thru 07/21/2017, 2018 thru 2024 RH® series trucks built 03/15/2017 thru 07/18/2023, 2004 thru 2009, 2011, 2012, and 2016 4400 model trucks built 12/01/2003 thru 10/17/2008, 07/30/2010 thru 09/09/2011, and 01/06/2025, 2013 7600 model trucks built on 10/30/2012, 2000 thru 2023 8100 model trucks built 01/04/2022 thru 08/30/2002, 2002 thru 2007 8500 model trucks built 08/24/2001 thru 08/07/2008, 2003 thru 2018 8600 model trucks built 06/27/2002 thru 12/08/2017, 2001 thru 2007 9400i built 03/14/2000 thru 03/19/2007, 2003 thru 2007, 2009 thru 2011, 2013 and 2017 9900i model trucks built 08/18/2002 thru 03/14/2007, 01/28/2008 thru 05/29/2010, 12/23/2011 thru 05/30/2012, and 02/19/2016 thru 11/25/2016, 2004 and 2007 9900iX model trucks built 04/10/2003 and 06/23/2006 thru 01/29/2007, 2010, 2011, 2013, and 2015 thru 2017 LoneStar® series trucks built 01/06/2009 thru 11/24/2010, 04/11/2012 thru 05/25/2012, and 04/16/2014 thru 05/18/2016, 2019 thru 2022 LS® series trucks built 03/02/2018 thru 09/20/2021, 2024 LS® built on 06/11/2023, 2017 thru 2024 LT® Series Trucks built 05/18/2016 thru 07/18/2023, and 2019 thru 2024 MV® Series trucks built 02/27/2018 thru 06/27/2023 with feature code 01WPN, 01WPS, or 01VAL (pintle hook, includes mounting bracket for lowering pintle hook) may not conform to Federal Motor Vehicle Safety Standard (FMVSS) 108, Lamps, Reflective Devices, and Assorted Equipment.

the vehicle must be equipped with an additional lamp or device of the same type. Specifically, Navistar did not equip these vehicles with additional unobstructed back-up lamps.

**RISK TO MOTOR VEHICLE SAFETY**

Back-up lamps that do not conform to all the requirements of FMVSS 108 while in bobtail mode and in reverse with obstructed back-up lamps may increase the risk of a vehicle crash.

**DEFECT REMEDY**

A remedy has been determined. Parts have been ordered and will be available in December Free of charge. When parts become available, you will be notified of additional actions you should take.

**ACTIONS YOU SHOULD TAKE**

To minimize the potential risk of this noncompliance, the operator should exercise greater caution while in bobtail mode and in reverse. **Your back-up lamp may not be completely visible to someone behind you.**

**If you are the lessor of this vehicle**, please forward a copy of this notice to the lessee within ten days to comply with federal regulations.

**IF YOU NEED FURTHER ASSISTANCE**

Navistar requests your prompt attention and patience regarding the correction of this defect and apologizes for any inconvenience this may cause you.

**Navistar, Inc.**

**REASON FOR THIS RECALL**

Certain trucks may not conform to Federal Motor Vehicle Safety Standard (FMVSS) 108 - If any required lamp or reflective device is obstructed by motor vehicle equipment,