



A PACCAR COMPANY

Customer Service Department
Kenworth Truck Company
P.O. Box 1000
Kirkland, Washington 98083-1000

IMPORTANT SAFETY RECALL INFORMATION



U.S. Department of
Transportation

Issued in Accordance
With Federal Law



PRESORTED
FIRST-CLASS MAIL
US POSTAGE
PAID
SEATTLE, WA
PERMIT NO. 2369

IMPORTANT SAFETY RECALL

Interim Notification



#



1

RECALL NOTICE

Subject: Safety Recall 23KWK: T660/T800/W900 Seatbelt Intermediate Connecting Point (ICP) Bar Spacer

December 13, 2023

IMPORTANT SAFETY RECALL **Interim Notification**

This notice applies to your vehicle: VIN: [REDACTED]

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Subject: Safety Recall 23KWK: T660/T800/W900 Seatbelt Intermediate Connecting Point (ICP) Bar Spacer
NHTSA Recall Number 23V717



Dear Kenworth Customer,

Kenworth Truck Company has decided that a defect, which relates to motor vehicle safety, exists in certain Model Year 2018 through 2024 T660/T800/W900 trucks built from 03/17/2017 through 03/10/2023 equipped with Sears Atlas 70 or 80 series seats.

An additional spacer was included in the joint connecting the seat structure to the seatbelt tether and buckle on certain seats. This additional spacer results in an increased moment arm on the seat structure, which increases the load on the joint. A failed Intermediate Connecting Point (ICP) bar may allow the seatbelt to slip when fully loaded by the weight of the seat occupant during a severe collision, which may increase the risk of injury.

The purpose of this letter is to notify you that Kenworth has initiated a recall campaign to remedy the defect. **At this time, replacement parts (seatbelt bolt) are not yet available from the component supplier.** You will be notified when the repair parts become(s) available and you may schedule an appointment with a dealer to obtain the repair.

<i>The problem is...</i>	A failed ICP bar caused by the added seatbelt spacer may allow the seatbelt to slip when fully loaded by the weight of the seat occupant during a severe collision, which may increase the risk of injury.
<i>What your dealer will do...</i>	Dealers will remove the additional seatbelt spacer, replace and re-torque a new shorter seatbelt bolt.
<i>What you must do ...</i>	When parts are available, contact your Kenworth Dealer to schedule an appointment for repair.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact Kenworth Customer Service using one of the following:

Email: Kenworth.Campaigns@paccar.com with the bulletin number in the subject line.
or

Mail: Kenworth Truck Company, P.O. Box 1000, Kirkland, WA 98083-1000, Attn: Customer Service Department.
or

Phone: 425-828-5888. In your message, provide a call back number, the last 8 digits of the VIN, and the bulletin number.

You may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>, if you believe that the manufacturer or dealer failed or was unable to remedy the defect without charge within a reasonable time following the earliest date upon which replacement parts become available.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Thank you,



Annick Hollingsworth
Director of Service Platforms
Kenworth Truck Company