

Toyota Motor North America, Inc.

Vehicle Safety & Compliance
Liaison Office
Mail Stop: W4-2D
6565 Headquarters Drive
Plano, TX 75024

June 22, 2023

AMENDMENT TO DEFECT INFORMATION REPORT (23V-142)

This amends Toyota's Part 573 Report of March 3, 2023 concerning the tonneau cover issue on certain Toyota vehicles.

The description of Corrective Repair Action is revised as noted below:

Description of Corrective Repair Action:

All known owners of the subject vehicles will be notified by first class mail to return their vehicles to a Toyota dealer. The dealer will install new hardware (bolts, spacers, washers, nuts, rubber washers and cotter pins) to the existing bracket and tonneau cover. If the tonneau cover has tears or splits at the mounting holes to the extent that new hardware cannot be installed, it will be replaced with a new tonneau cover and hardware. The remedy will be provided at no cost to the owners.