

SAFETY RECALL CAMPAIGN N785 – ENGINE COOLANT PIPE - RENEW

SAFETY RECALL N785 – ENGINE COOLANT PIPE - RENEW	
AFFECTED MODELS	19-21MY Range Rover 4 CYL PHEV 19-22MY Range Rover Sport 4 CYL PHEV
VOLUME AFFECTED	USA 2280 CAN 350
REPAIR	Affected vehicles will require replacement of a coolant system plastic intake pipe and a turbocharger coolant inlet pipe which can both be damaged due to engine overheating which can result from a water pump drive belt concern.
REPAIR TIME	1.7 hrs. +DIDO
CAMPAIGN LAUNCH	May 9th, 2023
Notes	Retailers should check the warranty portal to confirm affected VIN. All vehicles have been retailed and must be repaired at the next service visit. Owners will be notified via mail on May 26th, 2023