

**SAFETY RECALL CAMPAIGN N785 – ENGINE COOLANT PIPE - RENEW**

SAFETY RECALL N785 – ENGINE COOLANT PIPE - RENEW	
AFFECTED MODELS	19-21MY Range Rover 4 Cyl PHEV 19-22MY Range Rover Sport 4 Cyl PHEV
VOLUME AFFECTED	US 2280 CAN 350
REPAIR	Affected vehicles will require replacement of a coolant system plastic elbow and a turbocharger coolant feed pipe which can both be damaged due to engine overheating which can result from a water pump drive belt concern.
REPAIR TIME	TBA
CAMPAIGN LAUNCH	Retailer Notification: April 4th, 2023 Recall Repair Publication is expected to release on May 5th
Notes	Retailers should check the warranty portal to confirm affected VIN, all affected unsold vehicles must be held until repair can be performed. Parts are currently being procured. Owners will be notified via mail on May 26th, 2023