

**SAFETY RECALL N782 – INCORRECT REAR LAMP SPECIFICATION**

SAFETY RECALL N782 INCORRECT REAR LAMP SPECIFICATION	
AFFECTED MODELS	23MY Range Rover Sport
VOLUME AFFECTED	USA 5
REPAIR	A concern has been identified on certain vehicles where the incorrect specification rear lamps have been installed, which results in the turn signals flashing orange instead of the normal red and the bodyside brake lamps would be inoperative. Retailers must replace incorrect rear lamps with the correct service part.
REPAIR TIME	0.2 hrs. +DIDO
CAMPAIGN LAUNCH	April 21st, 2023
Notes	Owner notification is expected by June 2nd, 2023. Retailers should check the warranty portal to confirm affected VIN and following the bulletin service procedure, inspect/repair all affected vehicles at the next service visit.