

RECALLS N783 – SECOND ROW LEFT SEAT FRAME WELD

SAFETY RECALL N783 SECOND ROW LEFT SEAT FRAME WELD	
AFFECTED MODELS	22-23MY Range Rover
VOLUME AFFECTED	US 500 CA 51
REPAIR	A concern has been identified on certain Range Rover 7-seat vehicles where the second row left seat frame may have a latch installed with a defective weld. In vehicles that have a defective weld on the second row left seat frame latch, the seat may not be correctly secured. Warnings of a non-latch state are provided on the instrument panel cluster.
REPAIR TIME	TBC
CAMPAIGN LAUNCH	Retailer notification on April 20th, 2023 Service bulletin expected on May 22nd, when required parts are in stock
Notes	Owner notification is expected by May 29th, 2023. All affected units have been retailed.