

RECALL N789 and N768

SAFETY RECALL N789 – SECOND ROW SEAT ARMREST STOWAGE COMPARTMENT LATCH	
AFFECTED MODELS	22-23MY Range Rover 23MY Range Rover Sport
VOLUME AFFECTED	US 12587 CAN 832
REPAIR	A concern has been identified where the second-row seat armrest stowage compartment latch may fail. Retailers are to replace the latch with a new service part.
REPAIR TIME	TBA
CAMPAIGN LAUNCH	Retailer Notification: May 18th, 2023 Parts are being procured and expected to be available by July 24th, 2023
Notes	Owners will be notified via mail on June 30th, 2023

SAFETY RECALL N768 INCORRECTLY FITTED LOCKING MECHANISM ON THIRD ROW SEAT FRAME	
AFFECTED MODELS	23MY Defender 130 ONLY
VOLUME AFFECTED	US 812 CAN 82
REPAIR	A concern has been identified on a number of 2023 model year Land Rover Defender 130 vehicles with third-row seats, where an incorrect specification seat back latch component may have been installed on the third-row seat frame. Retailers will be required to replace the seat frame and associated components.
REPAIR TIME	0.1 to 2.9 + DIDO
CAMPAIGN LAUNCH	Retailers were notified on March 16th, 2023, and an inspection procedure was published March 28 th , 2023. Recall repair launched on June 1st, 2023
Notes	Failure rate is estimated to be 2%. All unsold vehicles must be held and cannot be sold until inspected or repaired. 7 open unsold vehicles as of June 5th, 2023 All customers will be notified by mail and asked to contact their retailer for a service appointment.