
Reference	SSM76024
Models	I-PACE / X590
Title	I-PACE Traction Battery Fault Detected warning message with P1B48-00 stored
Category	Electrical
Last modified	26-Jun-2023 00:00:00
Symptom	206000 Warning Indicators

Content Issue:
Amber warning message Traction Battery Fault Detected with DTC P1B48-00 Hybrid/EV Battery Voltage Deviation stored in the BECM. HV battery is unable to charge over 75% when this warning message and fault is stored.

Cause:
One or more internal cell faults have been identified in the HV battery pack

Action:
Do not perform any additional vehicle diagnostics. Raise a TA for for this concern.

anBhdHRicnM7MjAyMy0wNi0yN1QxNjoxOT01NC4wNTJaOzEzNj4yMjYyNTluMTEyOw==