

# IMPORTANT SAFETY RECALL INFORMATION

Issued in Accordance  
With Federal Law



## URGENT SAFETY RECALL NOTICE

Your **2022 JEEP JEEP WRANGLER SPORT** is under recall for Gear Position Sensor.

To schedule your recall repair contact your dealership or the FCA  
US Recall Team at **1-800-853-1403**.

Recall notice issued to:

[REDACTED]

Vehicle information:

VIN

[REDACTED]

**2022 JEEP JEEP WRANGLER SPORT**

Recall information: 92A/NHTSA 23V-641

Visit [recalls.mopar.com](https://recalls.mopar.com) for more information or call the FCA US Recall Team at  
**1-800-853-1403**

### Details of the Recall

The manual transmission on your vehicle may have been built with an improperly manufactured Gear Position Sensor / All Gear Sensor (AGS) which may cause the reverse lights and back-up camera to be disabled. Vehicles with a suspect gear position sensor / AGS may not display the rearview image or activate the backup lamps during a backing event. The vehicle operator will notice that the rearview image is not displayed if attempting to reference the image while backing. If this warning is not heeded, backing without verifying it is safe to do so could lead to an increased risk of injury to people outside the vehicle. Failure to illuminate the backup lamps may not adequately illuminate the roadway behind the vehicle or indicate to other drivers or pedestrians the intention to backup, which can cause a crash without prior warning. The condition described above does not comply with Federal Motor Vehicle Safety Standard (FMVSS) No. 571.111 S6.2.6 requires that "The rear visibility system default to the rearview image being visible and meet the requirements of FMVSS No. 571.111 S6.2.1 (field of view) and S6.2.2 (image size) at the beginning of each backing event, regardless of any modifications to the field of view that the driver had previously selected...". FMVSS No. 571.108 requires that backup lamps "Must be activated when the ignition switch is energized and reverse gear is engaged."

FCA US will repair your vehicle free of charge (parts and labor). To do this, your dealer will replace the Gear Position Sensor / AGS. The estimated repair time is 45 minutes. In addition, your

dealer will require your vehicle for proper check-in, preparation, and check-out during your visit, which may require more time. Your time is important to us, so we recommend that you schedule a service appointment to minimize your inconvenience.

## How do I schedule my **FREE** repair?

- ◆ Simply contact your Chrysler, Jeep®, Dodge or RAM dealer right away to schedule a service appointment.

*We apologize for any inconvenience, but are sincerely concerned about your safety. Thank you for your attention to this important matter.*

**Customer Assistance/Field Operations**

**FCA US LLC Team**

**[1-800-853-1403](tel:1-800-853-1403)**

**[recalls.mopar.com](http://recalls.mopar.com)**