

SAFETY RECALL N848 – TReK DEFENDER BRAKE CALIPER ADRIFT

SAFETY RECALL N848 – TReK DEFENDER BRAKE CALIPER ADRIFT	
AFFECTED MODELS	23MY Defender 130 TReK
VOLUME AFFECTED	US 121 CAN 0
REPAIR	A concern has been identified on US Land Rover Defender 130 vehicles that have been modified as part of the preparations for JLRNA's TReK event. During the vehicle preparation, re-installation of brake calipers did not follow the published repair procedure. If the brake calipers are not installed correctly, there is a risk the calipers may detach, resulting in degraded braking performance and possible structural damage to the wheel. Vehicles will require the brake caliper bolts, hoses and associated parts to be replaced following TOPIx workshop manual procedures.
REPAIR TIME	2.3 -2.4 hrs + DIDO
CAMPAIGN LAUNCH	Recall announced Dec 6 th , 2023. All affected vehicles must continue to be held until repaired. The Repair Bulletin release is waiting for parts receipts into the US PDC's. Target launch is before the end December.
Notes	Please refer to the warranty portal to identify affected vehicles which must not be sold or delivered until the repair has been completed. Retailers with affected vehicles were previously notified of this concern by email on Oct 31st, 2023.