

SAFETY RECALL N845 – OIL COOLER PIPE JOINT INTEGRITY CONCERN

SAFETY RECALL N845 – OIL COOLER PIPE JOINT INTEGRITY CONCERN	
AFFECTED MODELS	24MY Range Rover equipped with NC11 4.4L V8 engine
VOLUME AFFECTED	US 1520 CAN 219
REPAIR	A concern has been identified on certain vehicles where the fastener used to secure engine mounted oil cooler hoses, has been found to be inadequate and hoses are loose post assembly. Affected vehicles may require replacement of two studs with bolts, or where studs cannot be removed, replacement of the oil cooler pipes.
REPAIR TIME	Inspection and bolt replacement: 0.3 to 1.7 hrs + DIDO
CAMPAIGN LAUNCH	Inspection and bolt repair instructions were released on Nov 17th, 2023 Safety Recall Repair bulletin published Dec 6 th , 2023 including repair procedure for oil cooler pipe replacement, if required.
Notes	Please refer to the warranty portal to confirm affected vehicles. Any affected clients will receive a notification letter in January 2024.