

RECALL N830 – TAIL LAMP INOPERATIVE – WATER INGRESS

SAFETY RECALL N830 – TAIL LAMP INOPERATIVE – WATER INGRESS

AFFECTED MODELS	23MY Range Rover Sport
VOLUME AFFECTED	US 4359 CAN 560
REPAIR	A concern has been identified with the right-hand tailgate and body mounted rear lamps which may experience water ingress leading to one or more lamp failures including loss of brake/stop lamp, outer marker lamp, reversing lamp and turn signal indicator. Loss of rear right hand lamp system functionality increases the risk of a rear end crash. The tail lamp will need to be replaced.
REPAIR TIME	TBA
CAMPAIGN LAUNCH	Retailer Admin Bulletin: Launched on January 4th, 2024 Repair bulletin pending parts supply
NOTES	Please refer to the warranty portal to identify affected vehicles which must not be sold or delivered until the repair has been completed.