

RECALL N830 – TAIL LAMP INOPERATIVE – WATER INGRESS

SAFETY RECALL N830 – TAIL LAMP INOPERATIVE – WATER INGRESS	
AFFECTED MODELS	23MY Range Rover Sport
VOLUME AFFECTED	US 4359 CAN 560
REPAIR	A concern has been identified with the right-hand tailgate and body mounted rear lamps which may experience water ingress leading to one or more lamp failures including loss of brake/stop lamp, outer marker lamp, reversing lamp and turn signal indicator. Loss of rear right hand lamp system functionality increases the risk of a rear end crash. The RH rear tail lamps will need to be replaced.
REPAIR TIME	0.4 hrs. +DIDO
CAMPAIGN LAUNCH	Retailer Admin Bulletin: published on January 4th, 2024 Repair bulletin pending parts supply, expected in March
NOTES	All affected new vehicles have been retailed. Clients will be mailed an interim notification by February 9th ,2023. A 2 nd notification will be mailed when parts are available and repair appointments can be scheduled.