

## RECALL N830 – TAIL LAMP INOPERATIVE – WATER INGRESS

| SAFETY RECALL N830 – TAIL LAMP INOPERATIVE – WATER INGRESS |   |
|--|---|
| AFFECTED MODELS  | 23MY Range Rover Sport  |
| VOLUME AFFECTED  | US 4,359 CAN 560  |
| REPAIR   | A concern has been identified with the right-hand tailgate and body mounted rear lamps which may experience water ingress leading to one or more lamp failures including loss of brake/stop lamp, outer marker lamp, reversing lamp and turn signal indicator. Loss of rear right hand lamp system functionality increases the risk of a rear end crash. The RH rear tail lamps will need to be replaced. |
| REPAIR TIME  | 0.4 hrs. +DIDO  |
| CAMPAIGN LAUNCH  | Retailer Admin Bulletin: published on January 4th, 2024<br>Repair bulletin launched on March 22nd, 2024   |
| NOTES  | All affected new vehicles have been retailed. Clients have been mailed an interim notification on February 9 <sup>th</sup> , 2023. Clients will now be receiving a 2nd notification by mail.<br><br>Please refer to warranty portal to identify affected vehicles and complete this repair at the next service visit.   |