

RECALL N830 – TAIL LAMP INOPERATIVE – WATER INGRESS

SAFETY RECALL N830 – TAIL LAMP INOPERATIVE – WATER INGRESS	
AFFECTED MODELS	23MY Range Rover Sport
VOLUME AFFECTED	US 4,359 CAN 560
REPAIR	A concern has been identified with the right-hand tailgate and body mounted rear lamps which may experience water ingress leading to one or more lamp failures including loss of brake/stop lamp, outer marker lamp, reversing lamp and turn signal indicator. Loss of rear right hand lamp system functionality increases the risk of a rear end crash. The RH rear tail lamps will need to be replaced.
REPAIR TIME	0.4 hrs. +DIDO
CAMPAIGN LAUNCH	Retailer Admin Bulletin: published on January 4th, 2024 Repair bulletin pending parts supply, expected late March
NOTES	All affected new vehicles have been retailed. Clients will be mailed an interim notification by February 9 th , 2023. A 2 nd notification will be mailed when parts are available and repair appointments can be scheduled.