

INTEROFFICE MEMORANDUM

Original Publication Date: September 8, 2026

To: All Toyota Region and Private Distributor General Managers / Vice Presidents

From: Gary Ross
Vice-President, Product Quality and Service Support

**SAFETY RECALL CAMPAIGN RENOTIFICATION
OWNER RENOTIFICATION 25R004**

Toyota plans to conduct Safety Recall follow-up notifications to owners whose vehicles have not yet had the following campaign repair completed. Please note the following information for Regional and PD associates.

Campaign Covered in the Renotification

Campaign	Model, Model Year and Title	Approximate UIO	Renotification Schedule
23TA12	2020 – 2023 Highlander/ Highlander HV - Front Lower Bumper Cover Assembly May Detach While Driving	100,000	Mid-Sept

Follow-Up Owner Notification Timing

The Campaign Follow-Up Owner Notification will begin in mid Sept 2026. Owners will be notified using the following method(s):

- First Class Mail Letter
- Email

Additionally, dealers can conduct their own outreach using the available data in LEO for the list of campaigns called out in the table below.

List of Campaigns Currently in LEO

Campaigns in blue have an available Service on Demand (SOD) template in AMP, allowing dealers to notify customers about specific recalls and service campaigns via email or direct mail.

Campaign*	Model, Model Year and Title	Upload Date
20TA02	Multiple Models and Model Years - Vehicle May Stall During Driving at Higher Speed	Jan-2023
20TA03	Multiple Models and Model Years - Incomplete or Nondeployment of Airbags and/or Seat Belt Pretensioners May Occur	Apr-2021
20TA05	2011 - 2012 Model Year Corolla - Incomplete or Nondeployment of Airbags and/or Seat Belt Pretensioners May Occur	Apr-2021

20TC01	2012 Model Year Tacoma - Air Injection Pumps and Air Switching Valves	Oct-2021
21TA01	2009 - 2015 Model Year Venza - Non-deployment of Side and Curtain Shield Airbags May Occur	Jun-2022
21TA03	2018 - 2019 Model Year 86 - Vehicle May Stall if Low-Pressure Fuel Pump Becomes Inoperative	Sep-2022
21TA05	2019 - 2020 Model Year Yaris Sedan, 2020 Model Year Yaris Hatchback and Yaris R Vehicles - Vehicle May Stall During Driving at Higher Speeds	Jan-2023
21TA06	2018 - 2021 Model Year Tundra - Potential Increased Risk of Vehicle Fire	Jan-2023
21TA09	2018 - 2019 Model Year Camry - Sudden Loss of Power Braking Assist May Occur	Jan-2023
22TA02	2021 Model Year C-HR - Pre-Collision System (PCS) Inoperative without Warning Indicator	Dec-2023
22TA09	2022 Model Year Tacoma Vehicles - Upper Child Seat Anchor Welds May Fail During a Crash	Sep-2023
22TC01	Multiple 2021 - 2022 Model Year Vehicles - DCM (Data Communication Module) Reprogramming	Apr-2024
22TC05	Multiple Models and Model Years - Crankcase, Case Vent	Apr-2024
22TC07	2020 Model Year Corolla - Engine ECU Software Update	Feb-2023
23TA05	2023 Model Year Camry/Camry HV - DO NOT DRIVE - Potential Loss of Vehicle Control	Dec-2023
23TA09	2022 - 2023 Model Year Tundra and Tundra HV - Increased Risk of Fire	Apr-2025
23TA10	2022 Model Year GR86 - Turn Signal May Become Inoperative	Sept-2024
23TA12	2020 - 2023 Highlander/ Highlander HV - Front Lower Bumper Cover Assembly May Detach While Driving	Feb-2026
24TA01	2023 Model Year Mirai - PVM System May Not Display Required Images	Feb-2026
24TA04	2023 -2024 Model Year Camry/Camry HV - Rear Seat Head Rest Performance	Apr-2025
24TA05	2022 - 2023 Model Year Tacoma - Potential Axle Shaft Separation	Sept-2024
24TC01	2023 Model Year Corolla (Manufactured at TMMMS & TMC equipped with M20A engine) - Brake ECU reprogram	Oct-2025
24TC06	2024 Model Year Tacoma - Active Grille Shutter Engine Warning Light May Illuminate	Oct-2025

24TC08	2023 - 2024 Corolla HV / 2023 Prius / 2023 - 2024 Prius Prime - Fuel Tank Filler Clamp and Vapor Leak Detection	Jul-2026
25TA05	2021 - 2025 Model Year Sienna HV - Third Row Seat Back Performance	Jul-2026

*** Note:** If there are no VINs assigned to a specific dealer, that campaign code will not appear in the “Build List” function of LEO under “Recalls and Service Campaigns” List Type.

Customer Handling and Dealership Follow-Up

Toyota encourages dealerships to follow-up with their customers by telephone to urge them to complete any open Safety Recall and/or Service Campaign. A word track has been provided in the dealer letter for this purpose. To ensure a consistent and accurate description of a campaign is communicated to the customer, dealership associates are requested to refer to the specific campaign Q&A (available in TIS) to answer any specific customer questions.

Please review this entire package with your Service and Parts staff to familiarize them with the proper step-by-step procedures required to implement this Owner Renotification of Non-Completed Safety Recall, Special Service or Limited Service Campaign.

Thank you for your cooperation.
TOYOTA MOTOR SALES, U.S.A., INC