



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

February 22, 2024

Mr. Erik Blank
Manager, Product Safety
Honda (American Honda Motor Co.)
1919 Torrance Blvd
Torrance, CA 90501

NEF-107DC
24V-113

Subject: Fuel Pump May Fail

Dear Mr. Blank:

This letter serves to acknowledge Honda (American Honda Motor Co.)'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

HONDA/CBR1000RR/2018-2019
HONDA/CBR600RR/2018-2020
HONDA/GL1800/2018-2020

Mfr's Report Date: February 15, 2024

NHTSA Campaign Number: 24V-113

Components:

FUEL SYSTEM, GASOLINE:DELIVERY:FUEL PUMP

Potential Number of Units Affected: 17,374

Problem Description:

Honda (American Honda Motor Co.) is recalling certain 2018-2020 GL1800 (Goldwing), CBR600RR, and 2018-2019 CBR1000RR motorcycles. The fuel pump impellers may have been improperly molded, which can cause them to deform and result in fuel pump failure.

Consequence:

Fuel pump failure can cause an engine stall while driving, increasing the risk of a crash.

Remedy:

Dealers will inspect and replace the fuel pump module as necessary, free of charge. Owner notification letters are expected to be mailed April 8, 2024. Owners may contact Honda customer service at 1-866-784-1870. Honda's numbers for this recall are KP8, KP9, KQ0, and KQ1.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Honda (American Honda Motor Co.)'s contact for this recall will be Debora Crews who may be reached by email at debora.crews@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement