

# Part 573 Safety Recall Report

## 24E-017

**Manufacturer Name :** Braun Corporation**Submission Date :** FEB 15, 2024**NHTSA Recall No. :** 24E-017**Manufacturer Recall No. :** NR**Manufacturer Information :****Manufacturer Name :** Braun Corporation**Address :** 631 West 11 Street  
Winamac IN 46996**Company phone :** 1-800-488-0359**Population :****Number of potentially involved :** 92**Estimated percentage with defect :** 100 %**Equipment Information :****Brand / Trade 1 :** The Braun Corporation**Model :** NULC65S32X60I**Part No. :** NULC65S32X60I**Size :** NR**Function :** NR**Descriptive Information :** Premature outer barrier (OB) deployment**Production Dates :** DEC 09, 2021 - JUL 13, 2023**Description of Noncompliance :****Description of the Noncompliance :** Premature outer barrier (OB) deployment**FMVSS 1 :** 403 - Platform lift systems**FMVSS 2 :** NR**Description of the Safety Risk :** Premature outer barrier deployment can result in lack of platform wheelchair retention.**Description of the Cause :** Location of the ground sensing pressure switch**Identification of Any Warning that can Occur :** NR**Involved Components :**

Component Name : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : The Braun Corporation DBA BraunAbility

Address : 631 W 11th Street  
Winamac Indiana 46996

Country : United States

Chronology :

In February 2024, a BraunAbility customer performed testing outside of required scope and found under extreme conditions outer barrier deploys prematurely. BraunAbility performed investigation and validated the concern on 2/12/2024.

Description of Remedy :

Description of Remedy Program : Relocation of the switch from after the cylinder flow control valves to before the cylinder flow valve. A certified dealer will handle repairs of all impacted lifts. Dealer will be paid through warranty for labor time to complete the necessary repair of each product.

How Remedy Component Differs from Recalled Component : n/a

Identify How/When Recall Condition was Corrected in Production : The process of installing the pressure switch was corrected in production starting 2/13/2024. A revised manufacturing instruction was approved and published to production on 2/13/2024.

Recall Schedule :

Description of Recall Schedule : Dealers notifications will be sent 2/28  
Customer notifications will be sent on 3/13

Planned Dealer Notification Date : FEB 28, 2024 - FEB 28, 2024

Planned Owner Notification Date : MAR 13, 2024 - MAR 13, 2024

**Purchaser Information :**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

\* NR - Not Reported