



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

24V826

Manufacturer Name: Winnebago Industries, Inc.

Submission Date: Jun 02, 2025

NHTSA Recall No.: 24V826

Manufacturer Recall No.: 192

Manufacturer Information

Population

Manufacturer Name: Winnebago Industries, Inc.

Address: PO BOX 152
605 W. Crystal Lake Rd.
Forest City IA, 50436

Total number of potentially involved: 11,982

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2016-2025 Winnebago Vista

Product Category:

Product Type:

Fuel / Propulsion:

Production Dates: Jan 11, 2016 - Aug 24, 2024

Number of potentially involved:

Descriptive Information:

The recall population was determined by identifying the production dates.

Vehicle 2: 2016-2018 Itasca Sunstar

Product Category:

Product Type:

Fuel / Propulsion:

Production Dates: Jan 06, 2016 - Feb 15, 2018

Number of potentially involved:

Descriptive Information:

The recall population was determined by identifying the production dates.

Vehicle 3: 2015-2025 Winnebago Adventurer

Product Category:

Part 573 Safety Recall Report**24V826****Product Type:****Fuel / Propulsion:****Production Dates:** Jan 23, 2015 - Oct 10, 2024**Number of potentially involved:****Descriptive Information:**

The recall population was determined by identifying the production dates.

Vehicle 4: 2015-2018 Itasca Suncruiser**Product Category:****Product Type:****Fuel / Propulsion:****Production Dates:** Jan 23, 2015 - Oct 10, 2024**Number of potentially involved:****Descriptive Information:**

The recall population was determined by identifying the production dates.

Vehicle 5: 2014-2018 Winnebago Sightseer**Product Category:****Product Type:****Fuel / Propulsion:****Production Dates:** Jan 21, 2014 - Mar 02, 2018**Number of potentially involved:****Descriptive Information:**

The recall population was determined by identifying the production dates.

Vehicle 6: 2015-2024 Winnebago Commercial Vehicle**Product Category:****Product Type:****Fuel / Propulsion:****Production Dates:** Feb 14, 2015 - Oct 10, 2024**Number of potentially involved:****Descriptive Information:**

Part 573 Safety Recall Report**24V826**

The recall population was determined by identifying the production dates.

Vehicle 7: 2014-2018 Itasca Sunova

Product Category:

Product Type:

Fuel / Propulsion:

Production Dates: Jan 21, 2014 - Mar 02, 2018

Number of potentially involved:

Descriptive Information:

The recall population was determined by identifying the production dates.

Vehicle 8: 2016-2017 Itasca Solei

Product Category:

Product Type:

Fuel / Propulsion:

Production Dates: Jan 27, 2016 - Jul 05, 2016

Number of potentially involved:

Descriptive Information:

The recall population was determined by identifying the production dates.

Vehicle 9: 2018-2025 Winnebago Sunstar

Product Category:

Product Type:

Fuel / Propulsion:

Production Dates: Mar 19, 2018 - Aug 24, 2024

Number of potentially involved:

Descriptive Information:

The recall population was determined by identifying the production dates.

Vehicle 10: 2016-2025 Winnebago Forza

Product Category:

Product Type:

Fuel / Propulsion:

Part 573 Safety Recall Report

24V826

Production Dates: Jan 27, 2016 - Sep 26, 2024

Number of potentially involved:

Descriptive Information:

The recall population was determined by identifying the production dates.

Defect / Noncompliance Description

Description of the defect or noncompliance:

On certain Winnebago vehicles the adhesive application may have been done incorrectly on the hood mounting bracket(s).

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

The hood bracket(s) adhesive could potentially fail over time, resulting in the bracket separating from the vehicle. A detached bracket can become a road hazard, increasing the risk of a crash or injury.

Description of the cause:

On certain Winnebago vehicles the adhesive application was incorrectly applied or had incorrect prep work performed.

Identification of any warning that can occur:

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name: Winnebago Ind Inc.

Address: 605 W. Crystal Lake Rd
Forest City IA, 50436

Country: United States

Involved Components

Component Name 1: Hood Mounting Bracket

Part 573 Safety Recall Report

24V826

Component Description: Hood Mounting Bracket

Component Part Number: N/A

Chronology

In late August, Winnebago Product Safety was notified of a concern where a hood bracket had separated from the vehicle in transit. An investigation was subsequently opened. During the investigation, 344 total claims were identified, with some instances of completely detached hood brackets. On October 25, 2024, the Product Safety Committee met and decided the defect presented an unreasonable risk to safety. Winnebago is aware of 344 total claims that reference partial or full detachments occurring on the hood bracket(s). Winnebago is not aware of any injuries or property damage as a result of this condition. Final remedy is pending parts availability.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Inspect, Replace

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

Reimbursement requests will follow the general reimbursement plan on file with NHTSA.

How remedy component differs from recalled component:

There will be 3 different versions of the remedy with staggered launches between two groups. Remedy A applies to 2022-2025 Winnebago Vista, Sunstar, and Adventurer Motorhomes. Remedy A involves installing an additional mechanical fastener to support the existing adhesive.

Remedy B applies to 2016 - 2018 Winnebago Sightseer, 2016 - 2018 Itasca Sunova, 2016-2021 Winnebago Vista, 2018 - 2021 Winnebago Sunstar, 2016 - 2021 Winnebago Adventurer, 2015 - 2018 Itasca Suncruiser, 2016 - 2025 Winnebago Forza, 2016 - 2017 Itasca Solei, and 2016 - 2021 Itasca Sunstar Motorhomes. Remedy B will involve inspection and improving adhesive application to ensure the bracket(s) is/are fully adhered.

Remedy C applies to 2014 - 2015 Winnebago Sightseer, 2014 - 2015 Itasca Sunova, 2015 Winnebago Adventurer, 2015 - 2024 Winnebago Commercial Vehicles. Remedy C will involve installing an additional mechanical fastener with inspection and improving adhesive application.

Identify how/when recall condition was corrected in production:

The recall condition was corrected in production by performing the correct adhesion application on the hood mounting bracket(s).

Part 573 Safety Recall Report**24V826****Reimbursement Plan****Description of reimbursement program:****Period of reimbursement:****Costs to be reimbursed:****Address for reimbursement claims:****Recall Schedule****Description of recall schedule:**

Recall schedule for notifications will be within the 60 day requirement.

Planned Dealer Notification Date: No Dealers**Planned Interim Owner Notification Date:** No Owners**Planned Remedy Owner Notification Date:** Phased Recall**Date when VIN will be searchable:**