Manufacturer Name :BMW of North America, LLCSubmission Date :APR 24, 2024NHTSA Recall No. :24V-288Manufacturer Recall No. :NR

### Manufacturer Information :

Manufacturer Name : BMW of North America, LLC Address : P.O. Box 1227 Westwood NJ 07675-1227 Company phone : 18005257417

### Vehicle Information :

Vehicle 1:       2014-2015 BMW 2 Series Coupe (228i, 228i xDrive, M235i)         Vehicle Type:       LIGHT VEHICLES         Body Style:       2-DOOR         Power Train:       GAS         Descriptive Information:       Approximately 195 vehicles were equipped with a head air bag that may not have been produced by the supplier according to specifications.         Basis for recall population determination:       Vehicle manufacturing information and supplier production records were reviewed to determine the number and production date range of potentially affected vehicles.         Recall component difference to non-recall component:       The head air bag may not have been produced by the supplier according to specifications.         Production Dates:       DEC 04, 2013 - JUN 16, 2014       Image: NR       Image: NR       Image: NR       Not sequential					
Body Style :2-DOORPower Train :GASDescriptive Information :Approximately 195 vehicles were equipped with a head air bag that may not have been produced by the supplier according to specifications.Basis for recall population determination: Vehicle manufacturing information and supplier production records were reviewed to determine the number and production date range of potentially affected vehicles.Production Dates :DEC 04, 2013 - JUN 16, 2014				Coupe (228i, 228i xDrive, M2	235i)
Power Train :GASDescriptive Information :Approximately 195 vehicles were equipped with a head air bag that may not have been produced by the supplier according to specifications.Basis for recall population determination : Vehicle manufacturing information and supplier production records were reviewed to determine the number and production date range of potentially affected vehicles.Production Dates :Becall component difference to non-recall component: The head air bag may not have been produced by the supplier according to specifications.Production Dates :DEC 04, 2013 - JUN 16, 2014			LES		
Descriptive Information :Approximately 195 vehicles were equipped with a head air bag that may not have been produced by the supplier according to specifications.Basis for recall population determination: Vehicle manufacturing information and supplier production records were reviewed to determine the number and production date range of potentially affected vehicles.Production Dates :DEC 04, 2013 - JUN 16, 2014	00				
<ul> <li>been produced by the supplier according to specifications.</li> <li>Basis for recall population determination: Vehicle manufacturing information and supplier production records were reviewed to determine the number and production date range of potentially affected vehicles.</li> <li>Recall component difference to non-recall component: The head air bag may not have been produced by the supplier according to specifications.</li> <li>Production Dates : DEC 04, 2013 - JUN 16, 2014</li> </ul>	Power Train :	GAS			
Vehicle manufacturing information and supplier production records were reviewed to determine the number and production date range of potentially affected vehicles.Recall component difference to non-recall component: The head air bag may not have been produced by the supplier according to specifications.Production Dates :DEC 04, 2013 - JUN 16, 2014	Descriptive Information :				
The head air bag may not have been produced by the supplier according to specifications. Production Dates : DEC 04, 2013 - JUN 16, 2014		Vehicle manuf	facturing inf	ormation and supplier produ	
		The head air b	ag may not	-	
VIN Range 1 : Begin : NR End : NR Dot sequential					
	Production Dates :	DEC 04, 2013	-JUN 16, 20		
	Production Dates :	DEC 04, 2013	-JUN 16, 20	14	
					☐ Not sequential
					☐ Not sequential
					☐ Not sequential

The information contained in this report was submitted pursuant to 49 CFR §573



Number of potentially involved : 5,761

Estimated percentage with defect : 1%

**Population :** 

### 24V-288

24V-288

Page 2

	2014-2015 BN	AW 3 Series Seda	an (320i, 32	0i xDrive, 328i, 328i xD	rive, 335i, 335i
	xDrive, M3)				
• •	LIGHT VEHIC	LES			
Body Style :					
Power Train :					
Descriptive Information :				ped with a head air bag to specifications.	that may not have
	Vehicle manuf	0	ation and su	pplier production reco date range of potentiall	
	-	0 0		component: aced by the supplier acc	cording to
Production Dates :	NOV 26, 2013	- SEP 04, 2014			
VIN Range 1:		NR	End: NH	R	Not sequential
	Basis for recal Vehicle manua to determine Recall compo	I population dete facturing information the number and population nent difference to bag may not have	ermination: ation and su production o non-recall	pplier production reco date range of potentiall	y affected vehicles.
Production Dates :					
	Begin :	NR	End: NI	8	Not sequential

	LIGHT VEHIC 2-DOOR		oupe (428i, 428i xDrive, 4	435i, 435i xDrive, M4)
Descriptive Information :			les were equipped with a l lier according to specifica	head air bag that may not have tions.
	Vehicle manuf	facturing info		duction records were reviewed of potentially affected vehicles.
		oag may not h	e to non-recall componen ave been produced by the	
Production Dates : VIN Range 1 :		- APR 02, 201 NR	4 End: NR	Not sequential
Body Style : Power Train : Descriptive Information :	GAS Approximatel been produce Basis for recal Vehicle manuf to determine Recall compon	d by the supp Il population of facturing info the number at nent difference oag may not h	lier according to specifica determination: rmation and supplier proc	duction records were reviewed of potentially affected vehicles. t:
Production Dates : VIN Range 1 :		-JUL 09, 2014 NR	End: NR	☐ Not sequentia

#### **Description of Defect :**

FMVSS 1 :					
FMVSS 2 :	NR				
Description of the Safety Risk :	A rapid inflator separation could result in injury or fatality to vehicle occupants, and to persons who may be near the vehicle if this issue occurs.				
	Over time, if gas leaked from the inflator, then in a crash, this could result in partial inflation of the head air bag and result in insufficient restraint to a vehicle occupant, which could increase the risk of injury.				
Description of the Cause :	NR				
Identification of Any Warning that can Occur :	NR				
Involved Components :					
Component Name 1 : H	Iead Air Bag				
Component Description : H					
	7239399, 7239400, 7311201, 7311202, 7390327, 7390328				
Supplier Identification :					
Component Manufacturer					
Name : Autoliv Steering Wheels Mexico S. de R.L					
Address : 1320 Pacific Drive					
	Address : 1320 Pacific Drive Auburn Hills Michigan 48326				
Country: United States					
country. Cinted States					

**Chronology** :

The information contained in this report was submitted pursuant to 49 CFR §573

On April 12, 2024, BMW received information from the head air bag supplier that another vehicle manufacturer had decided to perform a safety recall involving certain head air bags. The supplier also indicated that certain BMW vehicles may also have been equipped with parts produced from corresponding production lots.

BMW reviewed the information provided by the supplier, and conducted its own engineering analysis.

On April 17, 2024, out of an abundance of caution, BMW decided to conduct a voluntary safety recall.

BMW is not aware of any customer complaints, concerns, and/or instances, dealer field reports, or warranty claims that relate, or may relate, to the issue identified in this report.

BMW has not received any reports, nor is BMW otherwise aware, of any incidents, accidents or injuries that relate, or may relate, to the issue identified in this report.

#### **Description of Remedy :**

Description of Remedy Program : The head air bags will be replaced.

Owners will be notified by First Class mail advising them of the recall and to schedule an appointment with an authorized BMW dealer to have the remedy performed for free. Although unlikely, owners who have had this remedy performed at their own expense prior to the recall notification, may be eligible for reimbursement according to BMW Group's reimbursement plan in accordance with 49 CFR 573.13 and 49 CFR 577.11.

How Remedy Component Differs NR from Recalled Component : Identify How/When Recall Condition NR

was Corrected in Production :

#### **Recall Schedule :**

Description of Recall Schedule :	Dealer notification is expected to begin and end on April 24, 2024.
	Owner notification is expected to begin and end on June 14, 2024.
Planned Dealer Notification Date : Planned Owner Notification Date :	

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573