Part 573 Safety Recall Report

Manufacturer Name :Rivian Automotive, LLCSubmission Date :MAY 23, 2024NHTSA Recall No. :24V-367Manufacturer Recall No. :FSAM-1445

Manufacturer Information :

Manufacturer Name : Rivian Automotive, LLC Address : 13250 North Haggerty Road PLYMOUTH MI 48170 Company phone : 999

Vehicle Information :

Vehicle 1:	2023-2024 Rivia	n R1S			
Vehicle Type :	LIGHT VEHICLES	5			
Body Style :	SUV				
Power Train :	NR				
Descriptive Information :	The recall population includes certain Model Year 2023 and 2024 R1T, R1S, and EDV vehicles that may have been built with headlamps aimed in such a way that they do not meet current production specifications. The suspect period began on April 07, 2023, when Rivian started to build vehicles with incorrectly aimed headlamps and ended on March 25, 2024, when Rivian stopped building vehicles with incorrectly aimed headlamps. That population was determined using manufacturing records. Similar vehicles not included in this recall have headlamps aimed to current production specifications.				
Production Dates :					
VIN Range 1:1		NR	End :	NR	☐ Not sequential
Vehicle Type :	2023-2024 Rivia LIGHT VEHICLES PICKUP TRUCK NR				
Descriptive Information :	The recall popula vehicles that may not meet current 2023, when Rivia ended on March aimed headlamp	y have been but t production sp an started to bu 25, 2024, wher s. That populat not included in	ilt with ecificati uild vehi n Rivian ion was	Model Year 2023 and 202 headlamps aimed in such ons. The suspect period l icles with incorrectly aim stopped building vehicle determined using manu- call have headlamps aime	a way that they do began on April 07, ed headlamps and s with incorrectly facturing records.
		1005 0004			
Production Dates :	SEP 09, 2023 - M	AR 25, 2024			



24V-367

Population :

Number of potentially involved : 2,334 Estimated percentage with defect : 100 %

Part 573 Safety Recall Report

24V-367

Page 2

Vehicle Type : L Body Style : V Power Train : N Descriptive Information : T 2 e 3 3 4 5	AN R ne recall population incluc chicles that may have been of meet current production 023, when Rivian started t nded on March 25, 2024, w med headlamps. That pop	n built with headlamps ain n specifications. The suspection o build vehicles with incom when Rivian stopped build	23 and 2024 R1T, R1S, and EDV ned in such a way that they do ect period began on April 07, rrectly aimed headlamps and ing vehicles with incorrectly sing manufacturing records. amps aimed to current
Production Dates : A	PR 27, 2023 - MAR 15, 202	24	
VIN Range 1 : Be		End: NR	☐ Not sequential
FMVSS 1 FMVSS 2 Description of the Safety Risk Description of the Cause Identification of Any Warning that can Occur	108 - Lamps, reflective of NR Headlamps that are not a of the road while driving at night. NR NR		ient
Involved Components :			
Component Name 1 : Component Description : Component Part Number :	US_LHD_LH, US_LHD_RH	464-P, PT00034392-R, PT	'00034389-R
The info	mation contained in this repo	rt was submitted pursuant to	49 CFR §573

Supplier Identification :

Component Manufacturer

Name : NR Address : NR NR Country : NR

Chronology:

On February 7, 2024, the Rivian vehicle manufacturing team identified a potential discrepancy in aiming between headlamp alignment stations and a manufacturing investigation began to identify the root cause and corrective actions.

From February 7, 2024, to May 17, 2024, Rivian conducted the investigation and identified the potentially affected vehicles.

On May 17, 2024, Rivian determined that a potential noncompliance to FMVSS 108, Lamps, reflective devices, and assoc. equipment cannot be ruled out.

As of the date of this filing, Rivian is not aware of any accidents or injuries related to this issue in any market.

Description of Remedy :

Description of Remedy Program :	Rivian will check the headlamp adjustment on the affected vehicles and correct it, if necessary. Rivian is committed to reimbursing owners for previous out-of-pocket repairs according to the plan submitted to the agency on May 10, 2022; however, systems affected by this recall are covered under Rivian's new vehicle limited warranties. Rivian only began releasing vehicles to customers at the end of 2021. As no owners of these vehicles would have reached the end of the warranty period and therefore not incurred expenses for the warranted repair as a result of this condition, no notification regarding reimbursement under section 577.11 is necessary. Rivian has a policy and practice of reimbursing owners who have paid for a repair that subsequently becomes the subject of a field action. To ensure consistency, Rivian, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.
	This recall is not related to a part defect, but rather an assembly issue. The remedy is to adjust the aim of the headlamps, if necessary.
Identify How/When Recall Condition was Corrected in Production :	NR

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Page 4

Recall Schedule :

Description of Recall Schedule :	We will mail notifications on or before July 06, 2024. As a direct-to consumer manufacturer, Rivian owns and operates all of the Company's sales and service operations. As all "dealers" are Rivian
	owned entities, notification will be through internal means to our licensed store and service operations addressing this recall on or before
	the date set forth in this response.
Planned Dealer Notification Date :	JUL 06, 2024 - JUL 06, 2024
Planned Owner Notification Date :	JUL 06, 2024 ⁻ JUL 06, 2024

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR $\S573$