OMB Control No.: 2127-0004

Part 573 Safety Recall Report

24V-409

Manufacturer Name: McClain Trailers, Inc.

Submission Date: JUN 06, 2024 NHTSA Recall No.: 24V-409 Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: McClain Trailers, Inc.

Address: 7203 COWART

PO BOX 202077 HOUSTON TX

77020-2077

Company phone: 999

Population:

Number of potentially involved : 140 Estimated percentage with defect : 100 %

Vehicle Information:

Vehicle 1: 2024-2024 MCCLAIN TRAILERS 10K, 12K, 15K, & 18K TRAILERS

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: ACTUATOR WAS MISLABELEDWITH A 20K GVWR RATING LABEL SHOULD READ

19K GVWR RATING

Production Dates: MAY 20, 2023 - JAN 05, 2024

VIN Range 1 : Begin : NR End : NR Not sequential

Description of Defect:

Description of the Defect: MISLABELED GVWR RATING AT 20K

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: NONE ON TRAILERS BULT WITH THIS ACTUATOR. EVERY TRAILER WE

BUILT HAD A GVWR RATING AT 18K OR LESS WITHIN THE CORRECT

RATING OF 19K

Description of the Cause: MISLABELED

Identification of Any Warning N/A

that can Occur:

Involved Components:

Part 573 Safety Recall Report

24V-409

Page 2

Component Name 1: 20K SURGE BRAKE COUPLER

Component Description: 20K SURGE BRAKE COUPLER

Component Part Number: 210-16-100 EQUIVALENT TO LIPPERT #2023050981-ACT-A19-ATUATOR

Supplier Identification:

Component Manufacturer

Name: LIPPERT

Address: 2020 BLAKESLEY PKWY

BRISTOL Indiana 46507

Country: United States

Chronology:

1/9/2024 - Lippert Engineering performed testing on the label rating.

1/25/2024 Lippert sent surge brake actuator to testing company for analysis. Results from independent testing company determined that the max rating should 19K.

2/9/2024 – Investigation of component completed. Set date to meet with the Safety Committee.

2/21/2024 - Safety Committee reviewed the information and concluded that the data reviewed indicated a unanimous vote for a voluntary recall. Investigation continued for to determine affected unit range.

2/26/2024 - Investigation concluded, range completed.

Description of Remedy:

Description of Remedy Program: IDENTIFY THE TRAILERS THAT ARE AFFECTED BY THE INCORRECT

LABEL, MAIL OUT CORRECT LABEL TO CHANGE OUT WITH CORRECT 19K

RATING

How Remedy Component Differs LABEL HAS CORRECT GVWR RATING

from Recalled Component:

Identify How/When Recall Condition NOTIFIED BY LIPPERT AND HAD NEW LABELS BROUGHT IN FOR

was Corrected in Production: CORRECT LABELING ON IN STOCK PARTS

Recall Schedule:

Description of Recall Schedule: IDENTIFY AFFECTED TRAILERS

CONTACT OWNERS MAIL CORRECT LABELS

Planned Dealer Notification Date: JUN 07, 2024 - JUN 28, 2024

The information contained in this report was submitted pursuant to 49 CFR §573

Part	573	Safety	Recall	Report
------	------------	---------------	--------	--------

24V-409

Page 3

Planned Owner Notification Date: JUN 28, 2024 - JUL 12, 2024

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573