OMB Control No.: 2127-0004

Part 573 Safety Recall Report

24V-441

Manufacturer Name : Thor Motor Coach

Submission Date: JUN 14, 2024 **NHTSA Recall No.:** 24V-441 **Manufacturer Recall No.:** RC000307



Manufacturer Information:

Population:

Manufacturer Name: Thor Motor Coach

Number of potentially involved: 35
Estimated percentage with defect: 100 %

Address: PO Box 1486

Estimated percentage with defect : 100 %

701 County Road 15 Elkhart IN 46515

Company phone: 877-500-1020

Vehicle Information:

Vehicle 1: 2023-2024 Thor Motor Coach Omni, Magnitude

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style: OTHER Power Train: DIESEL

Descriptive Information: The coach was designed with a exterior griddle option that partially blocks egress

from the emergency exit window when in use.

Production Dates: JUL 21, 2022 - JAN 29, 2024

VIN Range 1: Begin: 1FDFF6LTXNDA13755 End: 1FDFF6LT0RDA00101 ✓ Not sequential

Description of Defect:

Description of the Defect: When using the outside Griddle option, egress from the interior emergency exit

window is partially blocked by the griddle upon exit.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: During an emergency inside the motorhome egress may be blocked by the

griddle which may result in increased risk of personal injury.

Description of the Cause: The griddle option when in use blocks egress from the emergency exit window.

Identification of Any Warning None

that can Occur:

Involved Components:

Component Name 1: Outside Griddle Option 22" Blackstone

Component Description: Outside Griddle Option 22" Blackstone

Component Part Number: 0565455

Supplier Identification:

Component Manufacturer

Name: NR

Address: NR

NR

Country: NR

Chronology:

6/11/2024 - While reviewing the operation of the griddle option it was discovered that egress from the emergency exit window was partially blocked. A safety committee meeting was conducted the same day, and all agreed to issue a recall. No warranty claims or customer complaints have been received.

Description of Remedy:

Description of Remedy Program: Relocation of the emergency exit window to the other side of the

motorhome will be performed at no cost to the owner. Any

reimbursement will follow the general reimbursement plan that is on file

with NHTSA.

How Remedy Component Differs The remedy is to change the emergency exit window installed to the

from Recalled Component: opposite side of the motorhome. The griddle will no longer be in the path

of egress.

Identify How/When Recall Condition Engineering made the change online with production staff on 6/11/2024

was Corrected in Production: the same day it was discovered.

Recall Schedule:

Description of Recall Schedule: Thor Motor Coach has the utmost urgency in notifying owners about a

recall that affects their vehicle. Letters will be sent out once all pertinent

information has been gathered.

Planned Dealer Notification Date: AUG 14, 2024 - AUG 14, 2024

The information contained in this report was submitted pursuant to 49 CFR §573

Part 5	573	Safety	Recall	Report
--------	------------	--------	--------	--------

24V-441

Page 3

Planned Owner Notification Date: AUG 14, 2024 - AUG 14, 2024

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573