#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 24V-537

**Manufacturer Name:** Maserati North America, Inc.

Submission Date: JUL 18, 2024 NHTSA Recall No.: 24V-537 Manufacturer Recall No.: 730



#### **Manufacturer Information:**

Manufacturer Name: Maserati North America, Inc.

Address: One Chrysler Drive

Auburn Hills MI 48326

Company phone: 877-969-2737

### **Population:**

Number of potentially involved : 1,092 Estimated percentage with defect : 100 %

#### **Vehicle Information:**

Vehicle 1: 2023-2024 Maserati MC20 Cielo

Vehicle Type: LIGHT VEHICLES

Body Style : 2-DOOR Power Train : GAS

Descriptive Information: Some 2023-2024 MY MC20 Cielo vehicles may have been built with a non-compliant

tire placard reporting an incorrect Vehicle Capacity Weight ("VCW") value.

The suspect period began on July 19, 2021, when 2023 MY vehicle production began,

and ended on May 14, 2024, when

the VCW was corrected on the tire placard. Vehicle assembly plant records were used

to determine the suspect period.

Similar vehicles not included in this recall were built after the suspect period.

The total affected vehicles for this model is 380

Production Dates: JUL 19, 2021 - MAY 14, 2024

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2: 2022-2024 Maserati MC20

Vehicle Type: LIGHT VEHICLES

Body Style : 2-DOOR Power Train : GAS

Descriptive Information: Some 2022-2024 MY MC20 vehicles may have been built with a non-compliant tire

placard reporting an incorrect

Vehicle Capacity Weight ("VCW") value.

The suspect period began on July 19, 2021, when 2022 MY vehicle production began,

and ended on May 14, 2024, when

the VCW was corrected on the tire placard. Vehicle assembly plant records were used

to determine the suspect period.

Similar vehicles not included in this recall were built after the suspect period.

The total affected vehicles for this model is 712.

Production Dates: JUL 19, 2021 - MAY 14, 2024

#### **Description of Noncompliance:**

Description of the FMVSS 571.110 (S4.3) - Placard, requires that "each vehicle shall show...(a)

Noncompliance: vehicle capacity weight expressed as 'the

combined weight of occupants and cargo should never exceed XXX kilograms

or XXX pounds." Subject vehicles are

equipped with a tire placard label that does not correctly define the max

vehicle capacity weight

FMVSS 1: 110 - Tire selection and rims

FMVSS 2: NR

Description of the Safety Risk: A driver may rely on the incorrect VCW and overload the vehicle, which can

cause a vehicle crash without prior

warning.

Description of the Cause : NR

**Identification of Any Warning None** 

that can Occur:

#### **Involved Components:**

Component Name 1: Tire Placard Labels

Component Description: Tyres Data Plate

Component Part Number: 670222221

#### **Supplier Identification:**

#### **Component Manufacturer**

Name: Manufactured by Maserati

Address: NR

NR

Country: NR

#### **Chronology:**

On May 3rd, 2024, Maserati S.p.A was notified of a potential issue on certain vehicles related to the VCW on the tire label, potentially not in compliance with FMVSS No. 110.

On May 3rd, 2024, Maserati S.p.A opened an internal investigation and concluded in June 2024 that an issue existed on certain vehicles related to the tire placard values being incorrect, potentially resulting in a noncompliance with FMVSS No. 110.

On July 11, 2024, Maserati S.p.A determined, through the Vehicle Regulation Committee, to conduct a voluntary safety recall of the affected vehicles for the noncompliance of FMVSS 110.

#### **Description of Remedy:**

Description of Remedy Program: Maserati North America will conduct a voluntary recall to add an overlay

label to the tire placard. Maserati North America has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, Maserati North America, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the

expense.

How Remedy Component Differs: This recall is not related to a part defect but rather an engineering issue from Recalled Component: where the vehicle was built with incorrect data on the tire placard label.

Identify How/When Recall Condition Manufacturer label Data updated on VHS system at the manufacturing was Corrected in Production: plant on 05/14/2024 with corrected VCW values.

#### **Recall Schedule:**

Description of Recall Schedule: \*\*7/18/2024: Maserati North America, Inc., will notify dealers and begin

notifying owners on or about 09/04/2024.

Planned Dealer Notification Date: SEP 04, 2024 - SEP 04, 2024 Planned Owner Notification Date: SEP 04, 2024 - SEP 04, 2024

Part 573 Safety Recall Report	24V-537	Page 4
* NR - Not Reported		
The information contained in this report was submitted	d	