OMB Control No.: 2127-0004

Not sequential

Part 573 Safety Recall Report

24V-710

Manufacturer Name: General Motors, LLC

Submission Date: SEP 25, 2024 NHTSA Recall No.: 24V-710 Manufacturer Recall No.: N242474600



Manufacturer Information:

Manufacturer Name: General Motors, LLC

Address: 29427 Louis Chevrolet Road

MAIL CODE 480-210-2V WARREN MI

48093

Company phone: 586-596-1733

Population:

Number of potentially involved: 527 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2024-2024 Buick Envision

Vehicle Type: **Body Style:** Power Train: NR

Descriptive Information : GM's supplier identified the affected vehicles.

Production Dates: DEC 05, 2023 - DEC 29, 2023

VIN Range 1: Begin: NR End: NR

Description of Noncompliance:

Description of the General Motors has decided that certain 2024 model year Buick Envision Noncompliance: vehicles fail to conform to S4.3.3 of Federal Motor Vehicle Safety Standard

(FMVSS) No. 110 "Tire Selection and Rims." These vehicles are missing the label that provides the tire size and cold tire pressure for the front and rear

tires and the gross vehicle weight ratings.

FMVSS 1: 110 - Tire selection and rims

FMVSS 2: NR

Description of the Safety Risk: Without tire and gross vehicle weight rating information available on the

label, there is a risk that customers may overinflate or underinflate their tires or exceed the recommended weight ratings, increasing the risk of a crash.

Description of the Cause: The label was not installed by the GM supplier contracted to perform this work

at the port of entry.

Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name 1: LABEL-VEHICLE CERTIFICATION

Component Description: Certification Label

Component Part Number: 84822048

Supplier Identification:

Component Manufacturer

Name: Amports

Address: 1001 Navigation Blvd.

Freeport Texas 77541-5863

Country: United States

Chronology:

A GM supervisor submitted this issue to GM's Speak Up For Safety (SUFS) program on August 22, 2024 following notification from a dealer in Texas of approximately 20 Buick Envision vehicles with missing certification labels. GM opened a product investigation on August 30, 2024. GM's investigation found that the supplier did not install the certification label on the driver side lower B-pillar at the port of entry. On September 19, 2024, GM's Safety Field Action Decision Authority (SFADA) decided to conduct a noncompliance recall.

Description of Remedy:

Description of Remedy Program: Dealers will install the missing label.

Pursuant to 49 C.F.R. § 573.13(d)(1), all covered vehicles are under

warranty, so reimbursement is not offered.

How Remedy Component Differs The label installed by dealers will provide the correct tire size and cold tire

from Recalled Component: pressure for front, rear, and spare tires and the correct gross vehicle

weight ratings.

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: Dealers will be notified on September 25, 2024. Owner notification is

estimated to begin on November 11, 2024.

Planned Dealer Notification Date: SEP 25, 2024 - SEP 25, 2024

The information contained in this report was submitted pursuant to 49 CFR §573

Part	573	Safety	Recall	Report
-------------	------------	---------------	--------	---------------

24V-710

Page 3

Planned Owner Notification Date: NOV 11, 2024 - NOV 11, 2024

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573