

Dainese USA, Inc., 1001 Brioso Dr. Costa Mesa, CA 92627, Tel., +1 949 645 9500 ; Fax., +1 949 645 9501 Company subject to management and coordination by \$1 ield \$ p.A. - (Italy).

*** IMPORTANT SAFETY RECALL ***

NHTSA Recall 24E014

Recall of AGV Tourmodular DOT (E2206) Multi MPLK and Solid MPLK Motorcycle Helmets Read this entire letter carefully.

Stop sales of all affected AGV Tourmodular DOT (E2206) Multi MPLK and Solid MPLK **Motorcycle Helmets**

This notice applies to AGV Tourodular DOT (E2206) Multi MPLK and Solid MPLK helmets.

Helmet Models	Serial Number Range
AGV Tourmodular DOT (E2206) MPLK and Solid MPLK Motorcycle Helmets	06203P/J000239 - 06203P/J0001630

By Email and Federal Express










March 7, 2024



Dear

Dainese S.p.A is conducting a voluntary product safety recall of AGV Tourmodular DOT (E2206) Multi MPLK and AGV Tourmodular DOT (E2206) Solid MPLK helmets manufactured between February 1, 2022, and December 31, 2022. This recall affects all sizes, colors, and graphics packages for helmets within serial numbers 06203P/J000239 – 06203P/J0001630.

Our records indicate that Dainese may have sold one or more of the affected helmets to you. Immediately stop sales of all affected AGV Tourmodular DOT (E2206) MPLK and Solid MPLK motorcycle helmets. For any remaining in your inventory, please quarantine all affected helmets.

Please share this important safety notice with all your retailers in order to notify all retailers to stop sale of all recalled AGV Tourmodular DOT (E2206) MPLK and Solid MPLK motorcycle helmets.

WHY IS A RECALL BEING CONDUCTED?

The AGV Tourmodular DOT (E2206) helmet uses a chinstrap equipped with a micrometric buckle designed to automatically engage. Out-of-Tolerance sub-components in the micrometric buckle may, over time, result in the micrometric buckle not automatically engaging the buckle as intended by the design. If the buckle does not automatically engage and the user does not latch the buckle, the helmet may not be properly secured to the user's head. A helmet that is not securely fastened may not remain secure on a user's head during an accident, which increases the risk of severe injury or death.

A 573 Defect Information Report was submitted to NHTSA on February 13, 2024. (NHTSA Recall No. 24E014). A copy of the report is available publicly here: https://static.nhtsa.gov/odi/rcl/2024/RCLRPT-24E014-4050.PDF

HOW TO IDENTIFY AFFECTED HELMETS?









Affected products are AGV Tourmodular DOT (E2206) Multi MPLK and AGV Tourmodular DOT (E2206) Solid MPLK, including all sizes, colors, and graphic packs, with serial numbers 06203P/J000239 through 06203P/J0001630. AGV Tourmodular helmets with these serial numbers were included in Parts Unlimited/ Lemans purchase orders numbered: PO 210015621, PO 220005084, PO220005084-1, PO220005090, PO 220005093 and PO 220005093-1.

WHAT ARE WE DOING ABOUT THE PROBLEM?

Dainese submitted reports to the National Highway Trafffic Safety Administration and Health Canada. Dainese is performing a voluntary recall of AGV Tourmodular (E2206) motorcycle helmets. Dainese will repair all affected helmets free of charge.

WHAT SHOULD YOU DO?

Helmets Remaining in Your Inventory.

Distributors and dealers with unsold recalled units in inventory should stop all sales and quarantine all unsold recalled helmets. Dainese USA will contact you to coordinate and schedule the repair of all unsold helmets in your inventory.

Helmets Sold to Retailers.

Share this important safety notice with all your retailers in order to notify all retailers to stop sale of all affected AGV Tourmodular DOT (E2206) multi MPLK and AGV Tourmodular DOT (E2206) solid MPLK helmets.

All distributors are also asked to provide a list of all your retailers so that Dainese USA can also contact all retailers directly. The list of your retailers will be maintained as confidential. Please provide a list of retailers to Jeffrey Geiskopf at (949) 645-9500 #2 or by email at jeffrey.geiskopf@dainese.com. Dainese will notify these retailers and provide instructions for obtaining a helmet repair free of charge.

Helmets Sold to Consumers.

Distributors and dealers that previously sold these recalled helmets to consumers are asked to check internal records and provide their contact information to Jeffrey Geiskopf at (949) 645-9500 #2 or by email to jeffrey, geiskopf@dainese.com. Dainese will notify these owners using a NHTSA approved Part 577 owner







notification letter, beginning no later than on April 12, 2024. The customer notification letters will provide instructions for obtaining a helmet repair free of charge.

You must obtain the customer's full name, mailing address, telephone number and e-mail address and provide this information to Jeffrey Geiskopf at (949) 645-9500 #2 or by email to jeffrey Geiskopf@dainese.com.

If a customer returns a recalled helmet to your location, you must accept the recalled helmet.

It is a violation of Federal law for you to sell AGV Tourmodular DOT (E2206) Multi MPLK and AGV Tourmodular DOT (E2206) Solid MPLK motorcycle helmets covered by this notification. Substantial civil penalties apply to violations of this law.

QUESTIONS OR CONCERNS?

If you have questions or concerns about this recall, please contact Jeffrey Geiskopf at (949) 645-9500 #2; or by email at jeffrey.geiskopf@dainese.com.

Sincerely,

Fabio Alt

CFO

Dainese USA Inc.

Copy to:







