**Reference Number: GCUS-3-3257** 

REVISION: N232426400-04 - Safety Recall - Tailgate May Open Unexpectedly -

**Service Part Inspection** 

**GLOBAL SAFETY FIELD INVESTIGATIONS** 

DCS6906

**URGENT - DISTRIBUTE IMMEDIATELY** 

Date: May 31, 2024

Subject: REVISION: N232426400-04 – Safety Recall

Tailgate May Open Unexpectedly

Service Part Inspection Added

Models: 2020-2024 Chevrolet Silverado Heavy Duty (2500/3500 series)

2020-2024 GMC Sierra Heavy Duty (2500/3500 series)

Equipped with GATE FUNCTION-MANUAL ASSIST POWER RELEASE (RPO QT5)

To: All General Motors Dealers

This bulletin has been revised to update the service procedure to include a requirement to inspect the service part prior to installation. Please discard all previous copies of bulletin N232426400.

IMPORTANT: BEFORE INSTALLATION, YOU MUST INSPECT THE PART PER INSTRUCTIONS IN THE BULLETIN REVISION.

## Frequently Asked Questions Document (FAQs)

Attached to this message you will find a document that addresses the most likely questions customers may have regarding this Safety Recall. Please use this information as an aid to confidently answer customer concerns.

**END OF MESSAGE** 

**GLOBAL SAFETY FIELD INVESTIGATIONS**