Safety Recall 24KWF: Sheppard Steering Gear Sector Shaft

Number	
24KWF / 24V233 / 2024-197	
Supplier	
R. H. Sheppard Co., Inc.	
Description	
Sheppard Steering Gear Sector Shaft	
Date	
4/5/2024	
What's New	

SAFETY RECALL – INTERIM NOTIFICATION

Certain Kenworth vehicles from model year 2025 may contain steering gear(s) with a sector shaft that may not meet hardness requirements for the gear teeth due to improper heat treating during assembly. Sector shaft gear teeth with lower than required hardness may prematurely wear, crack, or fracture. A fractured gear tooth may interfere with the gear mechanism leading to binding which in turn may increase the likelihood of a crash.

This bulletin will be updated when repair parts and procedures are available.

Introduction

Certain Kenworth vehicles from model year 2025 may contain steering gear(s) with a sector shaft that may not meet hardness requirements for the gear teeth due to improper heat treating during assembly. Sector shaft gear teeth with lower than required hardness may prematurely wear, crack, or fracture. A fractured gear tooth

may interfere with the gear mechanism leading to binding which in turn may increase the likelihood of a crash. The driver may hear a popping sound when a tooth fractures.

This bulletin will be updated when repair parts and procedures are available.

Situation

686 (619 US and 67 Canada) Model Year 2025 T280/T380/T480/T680/T880/W990 chassis built from 10/03/2023 through 01/16/2024 with suspect steering gears.

Resolution

Safety Recall

INTERIM NOTIFICATION

This bulletin will be updated when repair parts and procedures are available.

Federal Law

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Links

Chassis List

US Customer Letter

Canada Customer Letter

Authored by: JK