

RECALL H491 – PASSENGER AIRBAG REPLACEMENT

SAFETY RECALL H491 – PASSENGER AIRBAG REPLACEMENT	
AFFECTED MODELS	21-23MY E-PACE
VOLUME AFFECTED	US 2409 CA 70
REPAIR	A concern has been identified on certain vehicles where, during a passenger airbag deployment, the airbag may tear as a result of the instrument panel airbag deployment door panel not being sufficiently weakened. A torn airbag may reduce the occupant protection, and therefore increase risk of injury in the event of a crash. A torn airbag may also allow the escape of hot gasses which may cause burns to occupants.
REPAIR TIME	1.1 hrs + DIDO
CAMPAIGN LAUNCH	Admin notification bulletin published May 2nd, 2024. Repair bulletin launched on August 20th
NOTES	Please refer to the warranty portal for affected vehicles and in BBSS to identify affected vehicles in inventory which cannot be delivered until the vehicle can be repaired.